SSIFIED	AFIT/	GE/EE	/80D-34		NORDQUI	ST	PERFO	NL	
0F 2									
									l
		Ì							
				·					
	) A	A .	A	) A		A I I I I I I I I I I I I I I I I I I I			

Acce	ssion For	
NTIS	GRA&I	
DTIC	TAB	
Unan	nounced 🗍	
Just	fication	
Ву		
Distr	ibution/	
Avai	lability Codes	
1	Avail and/or	
Dist	Special	- 1
1		- 1
1		- [
1 1		- [
	<del></del>	- 1

## THE EFFECT OF ROTOR GEOMETRY ON THE HARMONIC PERFORMANCE OF SYNCHRONOUS GENERATORS.

THESIS .

AFIT/GE/EE/80D-34

Cecil Stuerke Captain USAF David W. Nordquist Captain USAF



Approved for public release; distribution unlimited.

# THE EFFECTS OF ROTOR GEOMETRY ON THE HARMONIC PERFORMANCE OF SYNCHRONOUS GENERATORS

#### THESIS

Presented to the Faculty of the School of Engineering
of the Air Force Institute of Technology

Air Training Command
in Partial Fulfillment of the

Requirements for the Degree of

Master of Science

bу

Cecil Stuerke, B.S.

David W. Nordquist, B.S.

Captain

USAF

Captain

USAF

Graduate Electrical Engineering

December 1980

Approved for public release; distribution unlimited.

#### Preface

In the Air Force, there is a strong need for the lightest weight electrical generator with the highest possible efficiency. This brought about a thesis topic. In the topic it was proposed that two students investigate the effects of rotor geometry on improving the harmonic performance of a synchronous generator. If the harmonic performance could be improved enough, it was hoped that wave shaping circuitry external to the generator could be eliminated.

We chose this thesis topic because of the depth of our early graduate courses in power systems and our keen desire to increase our knowledge in this area.

We would like to thank Dr. Frederick Brockhurst for his guidance throughout all stages of this thesis effort. We would also like to thank Mr. James Kummeth for his assistance on the Finite Element analysis computer work.

Cecil Stuerke

David W. Nordquist

## Contents

																									Page
Prefa	ace	•	•		•	•		•		•	•	•		•		•	•			•		•		•	ii
List	οf	F	iguı	res					•											•	•	•		•	ν
List	οf	T	able	es					•		•		•								•			•	vi
List	of	S	ymbo	ols												•			•					•	vii
Absti	rac	t															•		•			•	•	•	хi
I.	I	nt	rodi	ıct	i or	ı		•											•				•	•	1
		]	Bacl Prob Assu Appi	ole:	m a	and	1 5	Sco	pe	;	•	•				•							•	•	1 4 5 5
II.	T	he	ory.																						7
III.	P	has	se 1	/o1	tag	ge	ar	ıd	Cu	rr	en	t	Wa	νe	9 5	Sha	аре	es		•					13
		(	Volt Volt Curi	en	e F t	Exa •	ımp	1e	•		•					•			•	•	•	•		•	13 18 21 21
IV.	A	rma	atui	re l	Rea	ct	ic	n						•	•					•		•	•		26
		]	Sing Dist Poly Exam	ri ph:	bu1 ase	ii e V	on Vir	Ex ldi	am	ıpl s	.е •			•	•	:	•	•	•	•	•		•	•	26 29 29 30
٧.	Ro	to	r M	ΛF		•											•								33
		E	xamp	ole	•									•	•									•	35
VI.	То	ta:	1 M	ИF																				•	37
		F.	ramt	\1e																					38

		Page
VII.	MMF Cancellation	40
	Armature Reaction MMF	40
	Example	43
	Example	44
VIII.	Reluctance Harmonic Control	46
	Flux Density	46
	Reluctance Specification Concept	48
	Methodology	50
	Example	51
	How Many Harmonics	55
	The Contradiction	56
		•
IX.	Incremental Reluctance Specification	58
	MMF to Flux Density	58
	Polustones Considiration	59
	Reluctance Specification	
	Example	60
	Triangular Phase Voltage Wave Shape Example .	61
Х.	Other Magnetic Effects	68
	Introduction	68
	Leakage Flux	69
	Fringing Flux	70
	Magnetic Saturation	71
	Finite Element Analysis	71
	Finite Element Analysis	11
XI.	Conclusions and Recommendations	75
	Conclusions	75
	Conclusions	76
	Recommendations	70
Bibliog	graphy	79
Annend	ix I: Sample Generator	81
Append	ix y. bample deficitor	01
Append	ix II: RGRID and TRIA Card Generation	85
Vita:	Captain Stuerke	106
Vita:	Captain Nordquist	107

## List of Figures

Figure		Page
1	Full Wave Bridge Rectifier	2
2	One Pole of the Rotor and the Stator	10
3	Phase Circuit Impedance	14
4	Phase Voltage Wave Shape Examples	16
5	Time Variation of the Chosen Internal Phase Voltage and Flux Density	20
6	Equivalent Circuit During Commutation	23
7	Time Variation of the Chosen Phase Current	24
8	Reluctance Harmonic Control Example Wave Shapes	54
9	Triangular Phase Voltage and Current Wave Shapes	67
10	Sample Generator Mesh Plot	74
11	Cross Section of the Sample Generator (Specifications and Dimensions)	84
12	Cross Section of the Sample Generator (RGRID and TRIA Cards)	87

## List of Tables

<u>Table</u>		Page
1	Normalized Current in Six Internal Phases versus Time	25
2	Normalized Spacial Component of Armature Reaction, $K(x,r)$ , at Slots of Phase C (Figure 2)	30
3	Normalized Total Armature Reaction MMF at Slots of Phase C	32
4	Rotor MMF	36
5	Total MMF at Phase C Slots versus Time	39
6	Space Harmonic Indexes for Armature Reaction Traveling Waves	44
7	Normalized Phase Current and Voltage (Triangle Wave Shape) (Figure 9a)	63
8	Normalized Armature Reaction MMF, Phase C Slots (Triangle Wave Shape)	64
9	Total MMF at Phase C Slots (Triangle Wave Shape)	65
10	Calculation of Incremental Reluctances (Triangle Wave Shape)	66
11	Sample Generator Dimensions and Specifications.	83

#### Greek Letter Symbols

- $\alpha_e$  Electrical angle between slots (electrical radians)
- $\delta$  Air gap distance (meters)
- $\Delta$  Incremental change
- ∞ Infinity
- λ Electrical angle of skew (electrical radians)
- μ Magnetic permeability (henries/meter)
- v Space harmonic number
- $\omega$  Frequency (hertz or radians/second)
- $\pi$  The constant Pi, 3.1415926535 .....
- φ Magnetic flux (webers)
- T<sub>n</sub> First harmonic rotor pole pitch (radians or slots)

#### Roman Letter Symbols

- A Internal generator phase
- A External generator phase
- A' Internal generator phase
- AC Alternating current
- $A_{\sigma v}$  Constant defined in Equation (26)
- a area (meters<sup>2</sup>)
- ag Coefficient of the Fourier series expansion of the phase current sine terms
- B Internal generator phase
- B External generator phase
- B Magnetic flux density magnitude (webers/meter<sup>2</sup>)

#### Roman Letter Symbols (continued)

- B' Internal generator phase
- $B_{\sigma \nu}$  Constant defined in Equation (32)
- B<sub>max</sub> Maximum amplitude of the magnetic flux density (webers/meter<sup>2</sup>)
- B<sub>TOT</sub> Total magnetic flux density (webers/meter<sup>2</sup>)
- B<sub>x</sub>(t)- Magnetic flux density at location x versus time (webers/meter<sup>2</sup>)
- bg Coefficient of the Fourier series expansion of the phase current cosine terms
- b<sub>p</sub> Rotor pole arc (radians or slots)
- b<sub>v</sub> Coefficient of the Fourier series expansion of the flux density space variation sine terms
- C Internal generator phase
- C' External generator phase
- $C_n$  Centers of reluctance increments on the rotor
- DC Direct current
- d Incremental width (seconds)
- g Time harmonic number
- I<sub>F</sub> Rotor current (amperes)
- I(t) Generator phase current versus time (amperes)
- I max Maximum generator phase current (amperes)
- K A proportionality constant defined in Equation (40)

### Roman Letter Symbols (continued) K(t,r) - Time MMF Variation K(x,r) - Space MMF variation - vth harmonic pitch factor K<sub>pν</sub> K<sub>dν</sub> - vth harmonic distribution factor vth harmonic skew factor Ksv k Integer constant - Magnetic path length (meters) - Effective rotor length (meters) Magnetomotive force (ampere-turns) MMF $MMF_{\mathbf{r}}(t)$ - MMF at location x versus time (ampere-turns) Maximum MMF as defined in Equation (18)(ampere-turns) ${\tt MMF}_{\tt rotor}$ - Rotor MMF (ampere-turns) MMF(x,t) - MMF as a function of distance and time (ampere-turns) MMF(x) -MMF versus distance - the space variation only (ampere-turns) MMF (t) - MMF reflected into the first slot (ampere-turns) Total number of internally generated phases m - Stator slot number n - Width of a phase belt (slots) q - Reluctance (henries<sup>-1</sup>) R Load resistance (ohms) $R_{L}$ - Root-Mean-Square RMS

#### Roman Letter Symbols (continued)

- $R_{x}(t)$  Reductance at location x versus time (henries<sup>-1</sup>)
- r Individual internal generator phase
- Number of turns of a coil group in a single stator slot
- $s_r$  Rotor coil turns
- T Period of a given waveform
- t Time (seconds)
- $v_{ang}$  Rotor angular velocity (radians/seconds)
- v Rotor tip velocity (meters/second)
- $V_{coil}$  Coil or coil group voltage (volts)
- $V_p$  Load voltage (volts)
- $V_{\sigma}$  Internally generated line to line voltage (volts)
- W Winding pitch (radians or slots)
- Distance along the circumference of the inside of the stator in stator coordinates (meters)
- x' Distance along the circumference of the rotor in rotor coordinates (meters)
- Z<sub>g</sub> Generator impedance (ohms)
- $\mathbf{Z}_{\mathbf{T}}$  Transmission line impedance (ohms)
- Z<sub>L</sub> Load impedance (ohms)

#### Abstract

The use of rotor geometry as a specification in the control of generator voltage and flux density harmonics is studied. The possibility of generating a specific voltage waveform at the load with only a three-phase rectifier between the AC generator and the load is investigated.

Since the specified load voltage is DC, the internally generated phase voltage waveform must be one which keeps constant the greatest instantaneous potential difference between any two phases.

The armature reaction MMF is expressed as an infinite set of traveling waves (with respect to the stator) with an infinite set of velocities. It is shown that the rotor MMF cannot cancel armature reaction everywhere because the rotor MMF has only the velocity of the rotor (not an infinite set of velocities).

The MMFs present at all the stator slots of an armature coil group are reflected into a single slot in an attempt to control the air gap flux density harmonics by selectively positioning increments of rotor reluctance. This method fails because a general solution for the reflected flux densities (appropriately synchronized with each other) could not be obtained. This method can be further investigated if such a general solution can be found.

Specifying the air gap reluctance incrementally as the rotor moves under successive stator slots is also tried as a means of harmonic control. This method proves unworkable due to negative MMF requirements and conflicting geometry specifications.

Finite Element analysis is introduced as a computer aid to the design of a magnetic structure. A specific computer program, MAGNETIC, is introduced. Another computer program is developed which generates input data for MAGNETIC. This input data is for the pole shoe and air gap regions of the generator. The program allows for a variable air gap shape.

Recommendations are included which may allow the successful specification of rotor geometry as a means of harmonic control, or which may prove the concept impossible.

## THE EFFECTS OF ROTOR GEOMETRY ON THE HARMONIC PERFORMANCE OF SYNCHRONOUS GENERATORS

#### I. Introduction

#### Background

For more than a decade, synchronous AC generators have been used to supply power to loads that require other than a pure sinusoidal AC voltage. The circuit configuration of a typical example is shown in Figure 1.

The AC generator, also called an alternator, allows sliprings to replace troublesome DC generator commutators. In the case of brushless AC generators, sliprings are even eliminated. In high voltage applications, AC generators have the additional advantages of a more easily insulated stationary armature (Ref 6:336).

In order to supply a non-sinusoidal voltage, a conventional AC generator requires external wave shaping circuitry. A DC load voltage requires that the AC generator output be rectified and also requires a large filter. A DC generator application may use a smaller filter, but this does not outweigh the commutator disadvantage.

The relative simplicity, reliability, and insensitivity to wear, corrosion, and breakage make AC generators beneficial even in DC applications (Ref 2:76) and (Ref 7). An AC generator with a tailored voltage output adds to these advantages.




Figure 1 Full Wave Bridge Rectifier

The voltage in each AC generator coil varies in time, but is not automatically sinusoidal. The voltage wave shape depends on the magnetic flux density field in the generator's air gap. The field is distorted due to the effects on salient pole geometry, conductor slots, and armature reaction. The time variation of the distorted voltage wave shape may be resolved into the sum of fundamental and higher order Fourier components.

The harmonics of the voltage time variation must be controlled. The first few harmonics contain significant power that the prime mover must supply. If the power from some of these harmonics must be trimmed from the load, it is generally dissipated as wasted heat in a conventional generator and filter circuit. Without proper control, the voltage wave shape inside the generator may have peaks that require increased armature insulation. An undesirably large and heavy generator is required to solve the preceding problems.

Conventional generator design includes methods for harmonic control. Generator geometry is normally used to suppress the most significant undesired harmonics. Specification of the distribution, pitch, and skew of the armature coils as well as the rotor pole arc provides a direct and effective means of harmonic control. If the wave shape can be trimmed to its fundamental component, the analysis necessary to

shape the waveform to the needs of the load is much easier. For any waveform, the shaping amounts to the reintroduction of properly sized higher harmonics at the expense of the fundamental.

When the generator is dedicated to specific load which requires other than the fundamental frequency voltage and current, the conventional design procedure is a disservice. If the voltage wave shape is obtained directly at the generator terminals, it is possible to meet the load power requirements with a smaller filter and at the same time reduce generator losses. Rotor geometry control can help provide the correct voltage at the generator terminals.

#### Problem and Scope

The purpose of this thesis effort is to investigate the possibility of generating a specific DC voltage waveform at the load with only a rectifier between the AC generator and the load. Rotor geometry modifications are to be investigated as the main means of control. This control method is applied to the generation of specific phase voltages (by controlling generator flux density harmonics) that will yield the desired load voltage using only rectification to modify the voltage wave shape. This effort reviews the theory by which rotor geometry and the voltage wave shape are related. From this basis, processes for determining a satisfactory rotor geometry are studied.

#### Assumptions

The attempts at rotor geometry determination through required reluctance do not account for the effects of finite permeability or flux fringing in the generator magnetic structure. These effects are considered negligible, but are discussed as they are observed in the finite element analysis (Section X). The basic generator design and the load parameters used in the development of numerical examples are assumptions taken from the generator design covered in Appendix I.

#### Approach and Presentation

Section I is an introduction. Section II reviews the theory through which the generator magnetic flux density is related to rotor geometry. This provides the basis for harmonic control.

In Section III, the load voltage requirements are used to select the waveform of the phase voltage and current. The specification of the phase voltage waveform determines the required magnetic flux density versus time in the generator. The specification of the phase current allows calculation of the armature reaction. Armature reaction MMF (magnetomotive force) is calculated in Section IV.

Section V develops an expression for the rotor MMF.

Section VI combines the armature reaction and rotor MMF in an expression for the MMF at the slots of a phase group versus time. An example is included.

Section VII discusses the limitations in the use of rotor MMF to cancel certain harmonics of armature reaction.

Section VIII describes an attempt to control the flux density harmonics with the introduction of selectively positioned increments of rotor reluctance. Reasons for the inapplicability of this approach are discussed.

Section IX describes the incremental specification of rotor reluctance as it is rotated into position under an armature coil. The insufficiency of this approach is also discussed.

Section X looks at the effects of finite permeability and flux fringing. Finite Element analysis is shown to be an excellent tool in fine tuning generator design to account for these effects.

Section XI recommends other approaches to the solution of the harmonic control problem for further research.

#### II. Theory

This section reviews the theory through which the generator magnetic flux density is related to rotor geometry. This discussion provides a basis for the control of the flux density harmonics.

In electromechanical energy conversion, the magnetic field is the intermediate stage. A rotating generator shaft causes magnetic lines of flux generated by the rotor coils to cut the armature coils. A voltage is induced in each coil according to Faraday's Law

$$V_{\text{coil}} = -d\phi/dt \tag{1}$$

where

 $v_{coil}$  is the instantaneous induced voltage

- φ is the magnetic flux in webers
- t is the time in seconds

The coil voltages combine as coil group voltage which combine as phase in voltages. The phase voltages are rectified to provide the load voltage.

"At a particular rotating speed, the instantaneous volts per conductor are proportional to the air gap flux density at the conductor. The wave shape of the conductor voltage versus time is therefore the same as that of the air gap flux density vs distance around the periphery." (Ref 3: Chap 6,6)

The phase voltage is shaped by both the flux density and the layout connection of the armature coils.

The shape of the flux density versus distance may be described as the sum of harmonic components. Each component contributes to the phase voltage. The stator coil's pitch, distribution, and skew determine multiplier factors which modify the voltage (Ref 5:44-55).

When the coil width is less than the width of a rotor pole, its voltage is modified by a pitch factor.

$$K_{pv} = \sin \left( \frac{v\pi}{2} \frac{W}{T_p} \right) \tag{2}$$

where

 $\boldsymbol{K}_{\text{pv}}$  is the vth harmonic pitch factor

v is the space harmonic number being considered

W is the winding pitch in radians or slots

T is the first harmonic rotor pole pitch in radians or slots

When the coils are not concentrically placed, the voltage is modified by a distribution factor.

$$K_{dv} = \frac{\sin(v\pi/m)}{q\sin(v\pi/qm)}$$
 (3)

where

 $K_{d\nu}$  is the vth harmonic distribution factor

q is the width of a phase belt in slots

m is the number of internally generated phases

When the coils are skewed with respect to the rotor axis, the voltage is modified by a skew factor.

$$K_{SV} = \sin \left( \frac{v \lambda / 2}{\lambda / 2} \right) \tag{4}$$

where

 $K_{SV}$  is the vth harmonic skew factor

The harmonics of the flux density are also controlled by the pole arc of a salient pole generator (b $_{\rm p}$  as shown in Figure 2). Reduction of the pole arc reduces leakage flux, but also reduces the magnitude of all the flux density harmonics as well. Unlike coil pitch, distribution, and skew, the actual magnetic field arc is affected by leakage and the level of magnetic flux saturation.

The typical use of the coil placement and pole arc factors is to eliminate certain undesirable flux density harmonics with minimum reduction of the fundamental. However, because these factors may be used to alter the relative magnitude of harmonics without cancellation, they are important in tailoring the phase voltage wave shape.

The flux density and therefore the phase voltage are shaped not only by the position of the current carrying conductors, but also by the geometry of the generator magnetic circuit.

Current in the stator coils and in the rotor coils are both sources of MMF rotating with respect to the stator.

The field produced by these MMF sources may be controlled through variation of the magnetic circuit reluctance.




Figure 2 One Pole of the Rotor and the Stator

$$\phi = MMF/R \tag{5}$$

where

MMF is the magnetomotive force in ampere turns  $R \quad \text{is the reluctance in henries}^{-1}$  Reluctance of the magnetic path is:

$$R = \ell_{\rm m}/\mu a \tag{6}$$

where

 $\mu$  is the permeability of the material in henries/meter

 $\ell_{m}$  is the path length in meters

a is the area in meters<sup>2</sup>

Because the permeability for air is much lower than the permeability of the generator steel, the air gap usually dominates the reluctance and the MMF drop around the magnetic circuit. The air gap reluctance (above the rotor) travels with respect to the stator as does the MMF which forces the flux through it.

If both sides of Equation (5) are divided by the area of the flux tube (Ref 1:245), in which the flux is found, it is evident that the flux density is related to the MMF through the length of the flux tube.

$$B = \mu MMF/\ell_{m}$$
 (7)

where

B is the magnetic flux density in webers/meter<sup>2</sup>
When the reluctance is due to the air gap distance, this becomes

$$B = \mu MMF/\delta(x)$$
 (8)

where

 $\delta(x)$  is the air gap distance in meters

x is the distance along the circumference of the inside of the stator in meters (stator coordinates)

The chosen method for tailoring the magnetic flux density is first to calculate the MMF variation at each slot, and then to adjust the reluctance through variation of the length of the air gap at the slots. The magnetic flux density in turn produces a phase voltage that becomes the desired voltage wave shape when rectified.

#### III. Phase Voltage and Current Wave Shapes

This section presents the theory and the selection of an acceptable phase voltage wave shape. The current wave shape which follows from the voltage is also presented. The load voltage requirement is the basic criteria on which the selections are based.

A number of different phase voltage wave shapes can produce the desired load voltage wave shape after being rectified. Thus, the harmonic content of the generator magnetic field that produces the voltage and current wave shapes is a design option.

#### Voltage

The generator must supply the required load voltage inspite of the generator transmission line impedances. If, as is shown in Figure 3, the load voltage is specified and the impedances are known, the required line to line voltage wave shape may be determined by circuit analysis.

$$v_{g} = v_{\ell} + \frac{v_{\ell}}{Z_{I}} (Z_{g} + Z_{T})$$
 (9)

where

 $v_{\rm g}$  is the internally generated line to line voltage

 $V_{\rho}$  is the required load voltage

 $Z_{\tau}$  is the load impedance in ohms




Figure 3 Phase Circuit Impedance

 $\mathbf{Z}_{\mathbf{g}}$  is the internal generator impedance in ohms

 ${\rm Z_T}$  is the transmission line impedance in ohms. This analysis is to be accomplished harmonic by harmonic from the components of the load voltage. Remember that the impedances are functions of frequency. It is the phase voltage leading to the composite  ${\it V_g}$  that must be induced in the armature coils by the aggregate magnetic field.

The shape of the desired load voltage wave shape specifies the phase voltage difference (between any two external generator phases) during the period in which it is applied to the load. This is because the three-phase rectifier applies the greatest instantaneous potential difference between any two phases to the load. If the load voltage is DC, the maximum phase difference is required to be constant. As the voltage in one phase falls below the necessary value, another phase must rise to replace it.

Equally loaded symmetrical phases will have identical voltage wave shapes. Successive phases will be evenly displaced through  $2\pi$  electrical radians of rotor rotation.

Example phase voltage wave shapes which meet the DC load requirements are shown in Figure 4. Notice that in Figure 4c, overlapping voltages are possible. In the ecases, current is supplied from more than two phases at a time.

The shape of the phase voltages as they transition is not specified by the load voltage requirements. It is




Figure 4 Phase Voltage Wave Shape Examples

unnecessary for the phase voltage transition to encourage proper current commutation because the current in the load is controlled by the applied voltage. The rate of change of the phase voltage may be limited in order to protect the silicon controlled rectifiers and/or diodes used in the three-phase rectifier.

Flexibility in the choice of the phase voltage wave shape is useful because this wave shape must be controlled by a properly engineered magnetic flux density in the air gap.

This flexibility may be exploited under rotor geometry control in order to accomplish flux density control with a minimum mean air gap. This will decrease leakage and improve generator performance. Because the phase voltage determines phase current, its shape also affects the magnetic field shape resulting from the armature reaction.

The shape of the load voltage during its application to the load and its transition affects its harmonic content. The proper choice of the phase voltage wave shape as it is applied to the three-phase rectifier may improve generator performance and/or simplify calculations. Once the effective rotor length, the rotor tip velocity, and the phase voltage are known, the required magnetic flux density is also known.

$$V_{\text{coil}} = Bv\ell$$
 (10)

where

 $V_{\rm coil}$  is the required coil group voltage

v is the rotor tip velocity in meters/second

l is the effective rotor length in meters

#### Voltage Example

See Appendix I (Generator Design) for a reference on the generator specifications used in this example.

For the example carried through this thesis effort, the desired load voltage is constant (DC). Although the internally generated phase voltage is properly derived from the desired load voltage according to Equation (9), this example begins with the specification of the line to line voltage. The value of the line to line voltage is chosen as 796.74 volts. This is  $\sqrt{3}$  times the RMS phase voltage of the sample sinusoidal AC generator. It is equal to the RMS voltage the generator could supply to a load if it were wye connected and if  $Z_{\overline{1}}$  and  $Z_{\sigma}$  were negligible.

The generator phase voltage output comes from the series connection of four coil groups (two coil groups per pole pair from the generator's two pole pairs). The selected internal phase voltage wave shape is shown in Figure 5. The rectification applies the maximum potential difference between any two external phases to the load. Considering that this difference is across two external phases and considering the

four coil groups in series per external phase, the required coil group voltage is:

$$V_{coil}^* = 796.74/8 = 99.59 \text{ volts}$$
 (11)

where

$$v_{coil}^*$$
 is the peak value of  $v_{coil}$ 

The rotor tip—speed (v) is 119.7 meters/second and the effective rotor length is .6438 meters. The total flux density which the five conductors in each coil group must cut has the same shape versus time as  $V_{\rm coil}$ . From Equation (10), the maximum flux density is:

$$B_{\text{max}} = \frac{v^*_{\text{coil}}}{v\ell} = 1.292 \text{ webers/meter}^2$$
 (12)

where

 $B_{\text{max}}$  is the maximum flux density in webers/meter<sup>2</sup>

Figure 5 gives the voltage versus time (external to the generator) for the three phases. Phase B lags phase A internally in the generator by  $\pi/3$  electrical radians (60 electrical degrees). Because phase B is connected in reverse, it lags phase A by an additional  $\pi$  electrical radians (180 electrical degrees) for a total lag of  $4\pi/3$  electrical radians (240 electrical degrees). The flux density for each phase has the same shape as the phase voltage variation.

By Fourier analysis, (Ref 14:Chap 2) the harmonic components of the desired total flux density per phase are given by:




Figure 5 Time Variation of the Chosen Internal Phase Voltage and Flux Density

$$B = \frac{4}{\pi} \sum_{g=1}^{\infty} B_{\text{max}} \frac{1}{g} \cos (g\pi/6) \sin (g\omega t)$$
 (13)

where

 $\omega$  is the frequency in radians/second g is the time harmonic number being considered

#### Current

The phase current versus time is determined by the shape of the phase voltage waveform as well as the circuit impedances. Between current commutation periods, the phase current is the specified load voltage divided by the specified load impedance. The value of the phase current during commutation may be determined by the use of harmonic component analysis (Ref 12:400). Because the circuit may have frequency dependant impedances, each harmonic component of the current may have a different angle by which it lags the voltage of the same harmonic. The composite waveform accounts for the current lag. Another approach is to analyze the composite voltage waveform directly (Ref 7).

#### Current Example

See Appendix I (Generator Design) for a reference on the generator specifications used in this example.

Because it is necessary to maintain the load power at 100 kilowatts, the DC load current is 125.51 amperes (100 kilowatts divided by  $460 \cdot \sqrt{3}$  volts). There are no parallel

current paths inside the generator. Therefore, between commutation periods, the phase current is also 125.51 amperes.

Figure 6 shows the circuit of Figure 1 during a phase B to a phase A commutation. Phase C is conducting throughout this time, so no diodes are shown. It is assumed that the transmission line impedance and the generator resistance are negligible.

The phase voltage wave shape was given in Figure 5. A constant voltage  $(4 \cdot V_{\text{coil}})$  is applied across the inductive coils of phases A and B. The current in phase B linearly increases from zero and the current in A linearly decreases toward zero. The generator phase inductance for this example is chosen such that the current commutation angle is  $\pi/9$  electrical radians or equivalently 20 electrical degrees.

The current wave shape of the three phases is given in Figure 7. Notice how they follow the voltages of Figure 5. The time variation of the current for the three phases at selected times is given in Table 1.

The harmonic components of the phase current are:

$$I(t) = \sum_{g=1}^{\infty} (36 I_{\text{max}}/g\pi^{2}) \left\{ \frac{\pi}{9} \left[ \cos(g\pi/9) - \cos(g2\pi/9) \right] + \frac{1}{g} \left[ \sin(g2\pi/9) - \sin(g\pi/9) \right] \right\} \sin g(\omega t - \pi/18)$$
 (14)

where

I(t) is the phase current in amperes  $I_{max}$  is the maximum value of the phase current




Figure 6 Equivalent Circuit During Commutation




Figure 7 Time Variation of the Chosen Phase Current

Table 1 Normalized Current in Six Internal Phases versus Time

TIME	PHASE						
(wt)	A	В	С	Α'	В'	C'	
-5π/15.	- 1	1	0	1	- 1	0	
-4π/15	-1	1	0	1	- 1	0	
-3π/15	- 1	1	0	1	- 1	0	
-2π/15	7	1	3	. 7	- 1	. 3	
-π/15	1	1	9	. 1	- 1	. 9	
0	0	1	- 1	0	- 1	1	
π/15	0	1	- 1	0	- 1	1	
2π/15	0	1	- 1	0	- 1	1	
$3\pi/15$	.3	.7	- 1	3	7	1	
4π/15	.9	. 1	- 1	9	1	1	
$5\pi/15$	1	0	- 1	- 1	0	1	
6π/15	1	0	- 1	- 1	0	1	
7π/15	1	0	- 1	- 1	0	1	
8π/15	1	3	7	- 1	. 3	.7	
9π/15	1	9	1	- 1	. 9	.1	
10π/15	1	-1	0	-1	1	0	

# IV. Armature Reaction

This section develops an expression for the time variation of the MMF at each of the stator slots due to armature reaction.

As magnetic lines of flux inside a generator cut armature coils, a voltage is induced at the armature terminals. When a load is connected to the generator, current will flow through the armature coils generating an MMF known as armature reaction. Armature reaction MMF opposes the MMF due to the rotor field.

When the MMF from the rotor coils is added to the armature reaction MMF, the total MMF is found. The desired magnetic flux density can be produced provided that the correct air gap reluctance is present.

#### Single-Phase Winding

A single coil from each pole of a single-phase winding produces a square MMF wave around the air gap circumference. If the coils span the full width of a pole  $(T_p)$ , each coil has a width of  $\pi$  electrical radians. The magnitude of the MMF wave will oscillate with the frequency of the current in the coils.

The MMF under the armature coils may be expressed as the product of the time variation of the coil current and the Fourier components of the space variation of the square MMF envelope. If the x coordinate (the distance along the circumference of the inside of the stator) is zero at a position which corresponds to the center of one of the full pitch coils, the space variation of the MMF per conductor is given by:

MMF(for one conductor) = 
$$I_{\text{max}} \frac{2}{\pi} \sum_{v=1}^{\infty} \frac{1}{v} \sin(v\pi/2) \cos(v\pi x/T_p)$$
 (15)

Because of the term  $\sin(\nu\pi/2)$ , the spacial variation has only odd harmonics. Because of the symmetry, MMF(-x) = MMF(x), the coefficient of the  $\sin(\nu\pi x/\tau_p)$  terms in Equation (15) are all zero (and not shown).

The current in the coils is the phase current as described in Section III.

$$I(t) = I_{\max} \sum_{g=1}^{\infty} (a_g \sin g\omega t + b_g \cos g\omega t)$$
 (16)

where

 $a_g$  are the coefficients of the sine current harmonics  $b_g$  are the coefficients of the cosine current harmonics Because:  $a\sin(\omega t + \phi) + b\cos(\omega t + \phi) = a'\sin\omega t + b'\cos\omega t$  a proper set of coefficients  $a_g$  and  $b_g$  may be established that account for the current lag angle of each harmonic. If, as is usually the case, the negative portion of the periodic current wave is a mirror image of the positive position, only odd harmonics exist in the time variation of the current.

A generator phase may contain several conductors distributed over one pole pitch in a single coil group. Since the current in each conductor is identical, the resultant MMF may be summed using the distribution factor  $K_{d\nu}$ . The space variation then becomes:

$$MMF(x) = MMF_{max} \frac{2}{\pi} \sum_{\nu=1}^{\infty} \frac{1}{\nu} \sin(\nu\pi/2) K_{d\nu} \cos(\nu\pi x/T_p) \qquad (17)$$

where

 $\operatorname{MMF}_{\max}$  is the maximum value of the MMF

$$MMF_{max} = qsI_{max}$$
 (18)

where

s is the number of turns of a coil group in a single stator slot

Notice that the coordinate x is now taken to be zero in the center of a coil group.

The space and time variation of a single phase is the product of the individual variations.

$$MMF(x,t) = MMF_{max} \left\{ \sum_{g=1}^{\infty} \left[ a_g \sin(g\omega t) + b_g \cos(g\omega t) \right] \right\}$$

$$\cdot \frac{2}{\pi} \sum_{v=1}^{\infty} \frac{1}{v} \sin(v\pi/2) K_{dv} \cos(v\pi x/T_p)$$
 (19)

where

· indicates a product

g is the time harmonic number being considered

### Distribution Example

See Appendix I (Generator Design) for a reference on the generator specifications used in this example.

The distribution factor for this example is:

$$\frac{\sin(\nu\pi/m)}{q\sin(\nu\pi/mq)} = \frac{\sin(\nu\pi/6)}{5\sin(\nu\pi/30)} \tag{20}$$

### Polyphase Windings

If there is more than one coil group above each pole, the phase of each coil group must be considered in calculating the resultant MMF. The current in each coil group is dependent upon the connection of the internal machine phases to the load. If there are m internal phases, there will be m possible different time variations of current in the stator. Each current wave shape will be equally distributed in time with a separation angle of  $2\pi/m$  electrical radians.

As the current reaches maximum in successive phases, the maximum fundamental MMF occurs at the center of the successive coil groups. Successive coil groups correspond to successive internal machine phases. The MMFs are therefore distributed  $2\pi/m$  electrical radians apart.

The MMF due to all of the phases combined is the maximum MMF times the product of the time K(t,r) and space K(x,r) variations for all of the m internal phases.

$$K(t,r) = \sum_{g=1}^{\infty} [a_g \sin g(\omega t + r2\pi/m) + b_g \cos g(\omega t + r2\pi/m)]$$
(21)

where

K(t,r) is the time MMF variation
r is the individual internal machine phase

$$K(x,r) = \frac{2}{\pi} \sum_{v=1}^{\infty} \left[ \frac{1}{v} \sin(v\pi/2) K_{dv} \cos v(\frac{\pi x}{T_p} + r2\pi/m) \right] (22)$$

where

K(x,r) is the space MMF variation

$$MMF(x,t) = MMF \sum_{max}^{m-1} \sum_{r=0}^{m-1} [K(t,r) \cdot K(x,r)]$$
 (23)

#### Example

See Appendix I (Generator Design) for a reference on the generator specifications used in this example.

The space variation term in Equation (22) converges as it is summed over the integer  $\nu$  from one to infinity. The resulting value of the expression for the six internal phases (r = 0 to r = 5) and for the position of the five slots in phase C (Figure 2) is given in Table 2.

Table 2 Normalized Spacial Component of Armature Reaction, K(x,r), at Slots of Phase C (Figure 2)

Phase	А	В	С	Α'	В'	C'
x r	0	1	2	3	4	5
π/30	. 5	. 5	4	5	5	. 4
3π/30	. 5	. 5	2	5	5	. 2
5π/30	. 5	. 5	0	5	5	0
7π/30	. 5	. 5	. 2	5	5	2
$9\pi/30$	. 5	. 5	. 4	5	5	4

With the current wave shape that was established in Section III, it is possible to evaluate the armature reaction MMF at each of the slots versus time. According to Equation (23) and using data from Table 1 and Table 2, the products of the time variation and the space variation may be summed over the applicable phases. The number of internal phases, m, is equal to six in this example.

Notice that both the time and the space variation terms for phase A' are opposite in sign from the entries for phase A. The product of the space and time variation terms leads to a magnetic field from A' which is equal to the magnetic field from A both in magnitude and sign. Likewise the phases B and B' and the phases C and C' produce similiar results. From Figure 2, a positive current in phase B produces an MMF under the slots of phase C which is opposite in direction to the MMF produced by a positive current in phase A.

The entries in Table 3 (Total Normalized Armature Reaction MMF) were obtained by changing the sign of the phase B and B' currents in Table 1 and by multiplying the resultant Table 1 array by the transpose of the array in Table 2. This multiplication is the direct normalized interpretation of Equation (23). In order to express the actual MMF, the entries must be multiplied by both the total number of conductors in series per internal machine phase and by the current which each conductor carries. Put another way, the entries in Table 3 multiplied by MMF<sub>max</sub> (Equation 18) will yield the actual MMF.

Table 3 Normalized Total Armature Reaction MMF at slots of Phase C

TIME x (wt)	π/30	3π/30	5π/30	7π/30	9π/30
-5π/15	-2.00	-2.00	-2.00	-2.00	-2.00
-4π/15	-2.00	-2.00	-2.00	-2.00	-2.00
-3π/15	-2.00	-2.00	-2.00	-2.00	-2.00
-2π/15	-1.46	-1.58	-1.70	-1.82	-1.94
-π/15	38	74	-1.10	-1.46	-1.82
0	20	60	-1.00	-1.40	-1.80
π/15	20	60	-1.00	-1.40	-1.80
2π/15	20	.60	-1.90	-1.40	-1.80
$3\pi/15$	.40	0	40	80	-1.20
$4\pi/15$	1.60	1.20	.80	.40	0
5π/15	1.80	1.40	1.00	.60	.20
6π/15	1.80	1.40	1.00	.60	.20
7π/15	1.80	1.40	1.00	.60	.20
8π/15	1.86	1.58	1.30	1.02	.74
$9\pi/15$	1.98	1.94	1.90	1.86	1.82
10π/15	2.00	2.00	2.00	2.00	2.00

#### V. Rotor MMF

This section develops an expression for the MMF due to the rotor coils.

The rotor coils are a significant source of MMF in the generator. Therefore, the affect on the controlled magnetic circuit must be accounted for.

Two different effects from the rotor are to be investigated in the search for a solution to the problem of harmonic control. In Section VII, the approach is to use the rotating rotor field MMF (rotating with respect to the stator) to cancel certain rotating MMF (again rotating with respect to the stator) components created by the armature reaction. This procedure requires a properly designed MMF over the rotor surface.

In contrast, Section VIII and Section IX capitalize on the reluctance of the rotor for control. For this case, the assumption is made that most of the MMF drop is across the air gap reluctance and that the rotor MMF may be represented (first order) as a square wave over the rotor surface. With these assumptions, the development of the rotor MMF expression and its translation into stator coordinates is continued.

Without fringing, the width of each square MMF pulse is equal to the rotor pole arc  $b_p$ . Therefore, the pitch factor  $K_{p\nu}$ , may be used to form the MMF expression.

MMF<sub>rotor</sub> = 
$$\frac{4}{\pi}$$
s<sub>r</sub> I<sub>F</sub>  $\sum_{\nu=1}^{\infty} \frac{1}{\nu} \sin (\nu \pi b_p / 2 T_p) \cos (\nu \pi x' / T_p)$  (24)

where

MMF<sub>rotor</sub> is the rotor MMF in ampere turns

s<sub>r</sub> is the number of turns in a rotor coil

I<sub>F</sub> is the rotor current in amperes

b<sub>p</sub> is the rotor pole arc in radians or slots

x' is the distance along the outside circumference of the rotor in meters (rotor coordinates)

The zero (origin) of the rotor coordinate system is taken at a pole center.

The MMF expression for non-constant MMF across the pole face may also be achieved by Fourier analysis. In this case, saturation and fringing are the means of achieving the desired effect. Finite Element analysis (Section X) is an important tool to use when considering saturation and fringing.

Each harmonic component of the rotor MMF travels with respect to the stator and has the same velocity as the rotor. The MMF due to the rotor can be transformed into the stator's set of polar coordinates by transforming each harmonic component into a forward traveling wave.

$$MMF_{rotor} = \frac{4}{\pi} s_r I_F \sum_{v=1}^{\infty} \frac{1}{v} \sin \left( v \pi b_p / 2 T_p \right) \cos \left[ \left( v \pi x / T_p \right) - v \omega t \right]$$
(25)

The MMF which drives a flux tube may be moved around that tube without changing the flux density. Therefore with radial flux lines, the traveling square wave can be projected across the air gap with the same angular coordinates.

As was true of the armature MMF expression, the rotor MMF versus time can be evaluated at any x by substitution of that value. Rotor MMF is opposed by the armature reaction MMF. The MMFs may be algebraically summed to obtain an expression for the total MMF along the stator (Section VI).

# Example

See Appendix I (Generator Design) for a reference on the generator specifications used in this example.

The chosen pole arc is  $2\pi/3$  electrical radians. There are 533 ampere turns in each rotor winding. The rotor MMF is a square wave which travels with the rotor under the armature coils. The time variation of the rotor MMF under the slots of phase C (Figure 2) is given in Table 4.

Table 4 Rotor MMF

TIME x (ωt)	π/30	3π/30	5π/30	7π/30	9π/30
-5π/15	0	0	0	0	0
-4π/15	533	0	0	0	0
-3π/15	533	533	0	0	0
$-2\pi/15$	533	533	533	0	0
-π/15	533	533	533	533	0
0	533	533	533	533	533
π/15	533	533	533	533	533
2π/15	533	533	533	533	533
3π/15	533	533	533	533	533
4π/15	533	533	533	533	533
5π/15	533	533	533	533	533
6π/15	0	533	533	533	533
7π/15	0	0	533	533	533
8π/15	0	0	0	533	533
9π/15	0	0	0	0	533
10π/15	0	0	0	0	0

### VI. Total MMF

Section IV developed an expression for the armature reaction MMF and Section V developed an expression for the rotor MMF. These MMFs are superimposed in the generator's air gap. Each MMF produces a magnetic flux density with space and time variations that are superimposed. This section develops an expression for the total MMF.

At first glance it seems possible to calculate the flux density due to armature reaction and then to adjust the rotor reluctance so the rotor MMF produces a cancelling flux density. This idea is flawed because a change in the magnetic circuit also changes the magnetic flux density driven by the armature reaction MMF. Therefore, instead of the superposition of flux density, it is the superposition of the MMF which must be accomplished. The desired flux density may then be obtained from the total MMF by adjusting the air gap reluctance.

The total MMF in the generator is the sum of the expressions in Equation (23) and Equation (25). Because of the direction defined for positive current (Figure 2), the armature reaction MMF and the rotor MMF add.

As is shown in Section VII, specification of rotor MMF is not sufficient to control the generator MMF for all of the air gap for all times. The armature reaction MMF produces both space and time variations that are not controlled by the

rotor MMF. Substitution of the space or the time into the expressions however, brings the terms of both the armature reaction MMF and the rotor MMF to a countably infinite series. The coordinates of the stator conductors are important since it is at these points that the time variation of the flux density creates the desired voltage wave shape. With this substitution, control of the harmonics is approached in Section VIII and Section IX.

# Example

See Appendix I (Generator Design) for a reference on the generator specifications used in this example.

The actual armature reaction MMF is obtained by multiplying the normalized armature reaction MMF in Section IV by  $\text{MMF}_{\text{max}}$  (Equation 18). The total MMF can be obtained by summing the armature reaction MMF and the rotor MMF. This is equivalent to multiplying Table 3 by  $\text{MMF}_{\text{max}}$  and adding the result to Table 4. The total MMF is shown in Table 5.

Table 5 Total MMF at Phase C Slots versus Time

TIME x (ωt)	π/30	3π/30	5π/30	7π/30	9π/30
-5π/15	-1255.1	-1255.1	-1255.1	-1255.1	-1255.1
-4π/15	-722.1	-1255.1	-1255.1	-1255.1	-1255.1
-3π/15	-722.1	-722.1	-1255.1	-1255.1	-1255.1
-2π/15	-383.2	-458.5	-533.8	-1142.1	-1217.4
-π/15	294.5	68.6	-157.3	-333.2	-1142.1
0	407.5	156.5	-94.6	-345.6	-596.6
π/15	407.5	156.5	-94.6	-345.6	-596.6
2π/15	407.5	156.5	-94.6	-345.6	-596.6
$3\pi/15$	784.0	533.0	282.0	31.0	-220.0
4π/15	1537.1	1286.1	1035.0	784.0	533.0
5π/15	1662.6	1411.6	1160.6	909.5	658.5
6π/15	1129.6	1411.6	1160.6	909.5	658.5
7π/15	1129.6	878.6	1160.6	909.5	658.5
8π/15	1167.2	991.5	815.8	1173.1	997.4
9π/15	1242.5	1217.4	1192.3	1167.2	1675.1
10π/15	1255.1	1255.1	1255.1	1255.1	1255.1

# VII. MMF Cancellation

This section considers rotor MMF for the cancellation of selected armature reaction MMF harmonic components. For this analysis, it is useful to express both the armature reaction MMF and the rotor MMF as traveling waves.

#### Armature Reaction MMF

Equation (23) is the expression for the armature reaction MMF. Symmetry about the time origin causes the cosine terms in K(t,r) (Equation 21) to be zero. The cosine term due to asymmetry is subsequently considered. For a given g and  $\vee$ , several constants from Equation (23) may be combined by letting:

$$A_{gv} = \frac{2}{\pi} qs I_{max} a_g sin (v\pi/2) K_{dv}/v$$
 (26)

where

 $A_{gv}$  is a constant whose value depends on g and v Remembering that the cosine coefficient in Equation (21) is zero, the armature reaction MMF expression from Equation (23) can be rewritten as:

$$MMF(x,t) = \sum_{g=1}^{\infty} \sum_{v=1}^{\infty} \sum_{r=0}^{m-1} A_{gv} \sin g(\omega t + r2\pi/m)$$

$$\cdot \cos v[(\pi x/T_p) + (r2\pi/m)] \qquad (27)$$

Using the trigonometric identity

$$\sin(\alpha)\cos(\beta) = \frac{1}{2}\sin(\alpha - \beta) + \frac{1}{2}\sin(\alpha + \beta)$$
 (28)

Equation (27) may be rewritten as:

$$\begin{split} & \text{MMF}(x,t) = \sum_{g=1}^{\infty} \sum_{v=1}^{\infty} \frac{1}{2} A_{gv} \cdot \\ & \left\{ \sin \left[ (g\omega t) + v\pi x/T_p \right] \right. + \sin \left[ (g\omega t) - (v\pi x/T_p) \right] \\ & + \sin \left[ (g\omega t) + (v\pi x/T_p) - (g+v)\frac{2\pi}{m} \right] \right. + \sin \left[ (g\omega t) - (v\pi x/T_p) - (g-v)\frac{2\pi}{m} \right] \\ & + \sin \left[ (g\omega t) + (v\pi x/T_p) - (g+v)\frac{4\pi}{m} \right] \right. + \sin \left[ (g\omega t) - (v\pi x/T_p) - (g-v)\frac{4\pi}{m} \right] \\ & \vdots \\ & \vdots \\ & + \sin \left[ (g\omega t) + (v\pi x/T_p) - (g+v)\frac{(m-1)2\pi}{m} \right] + \sin \left[ (g\omega t) - (v\pi x/T_p) - (g-v)\frac{(m-1)2\pi}{m} \right] \right\} \end{split}$$

Equation (29) contains the positive direction (terms in the right column of the equation) and negative direction (terms in the left column of the equation) traveling waves.

When  $\psi$  is a multiple of m,

$$\sin \Theta + \sin (\Theta + \psi \frac{2\pi}{m}) + \sin (\Theta + \psi \frac{4\pi}{m}) + \dots + \sin (\Theta + \psi \frac{(m-1)2^{\pi}}{m}) = m \sin \Theta$$
(30a)

When  $\psi$  is not a multiple of m,

$$\sin \Theta + \sin (\Theta + \psi \frac{2\pi}{m}) + \sin (\Theta + \psi \frac{4\pi}{m}) + \dots + \sin (\Theta + \psi \frac{(m-1)2\pi}{m}) = 0$$
(30b)

This also holds true for a cosine sum with equivalent arguments.

Because the use of sines and cosines in K(t,r) preserves symmetry about the origin, g and  $\nu$  are both odd integers. Therefore, their sums and differences must be even.

With  $\psi$  analogous to  $(g + \nu)$  or  $(g - \nu)$  in Equations (30a) and (30b)

$$MMF(x,t) = \sum_{g=1}^{\infty} \sum_{v=1}^{\infty} \left[ \frac{m}{2} A_{gv} \sin(g\omega t + \frac{v\pi x}{Tp}) + \frac{m}{2} A_{gv} \sin(g\omega t - \frac{v\pi x}{Tp}) \right]$$
(31)

where for the first sine term (g+v) is an even multiple of m and for the second sine term (g-v) is an even multiple of m.

When the cosine term in K(t,r) is not zero, the traveling waves may also be found. When

$$B_{gv} = \frac{2}{\pi} qs I_{max} b_g sin (v\pi/2) K_{dv}/v$$
 (32)

where

 $$B_{\mbox{\scriptsize g}\nu}$$  is a constant whose value depends on g and  $\nu$  the cosine term in Equation (21) leads to:

$$MMF(x,t) = \sum_{g=1}^{\infty} \sum_{\nu=1}^{\infty} \sum_{r=0}^{\infty} B_{g\nu} \cos g(\omega t + r2\pi/m) \cos \nu [(\pi x/T_p) + (r2\pi/m)]$$
(33)

The trigonometric identity

$$\cos(\alpha) \cos(\beta) = \frac{1}{2} \cos(\alpha+\beta) + \frac{1}{2} \cos(\alpha-\beta)$$
 (34)

yields:

$$MMF(x,t) = \sum_{g=1}^{\infty} \sum_{\nu=1}^{\infty} \left[ \frac{m}{2} B_{g\nu} \cos(g\omega t + \frac{\nu\pi x}{T_p}) + \frac{m}{2} B_{g\nu} \cos(g\omega t - \frac{\nu\pi x}{T_p}) \right]$$
(35)

where for the first cosine term (g + v) is an even multiple of m and for the second cosine term (g + v) an even multiple of m.

Therefore, the complete expression for the time variation of the magnetic field (armature reaction MMF only) referenced to a fixed stator due to the specified m<sup>th</sup> internal phase armature current is:

$$MMF(x,t) = \sum_{g=1}^{\infty} \sum_{v=1}^{\infty} \left[ \frac{m}{2} A_{gv} \sin(g\omega t + v \frac{\pi x}{T_p}) + \frac{m}{2} B_{gv} \cos(g\omega t + v \frac{\pi x}{T_p}) \right]$$

$$+ \frac{m}{2} A_{gv} \sin(g\omega t - v \frac{\pi x}{T_p}) - \frac{m}{2} B_{gv} \cos(g\omega t - v \frac{\pi x}{T_p}) \right]$$
(36)

As before, for the first two terms, (g + v) is an even multiple of m and for the last two terms, (g - v) is an even multiple of m.

#### Example

See Appendix I (Generator Design) for a reference on the generator specifications used in this example.

For m=6, the terms of Equation (36) are non-zero when (g+v) or (g-v) is a multiple of 6. Therefore,

$$v = + 6k - g \tag{37}$$

where

k is an integer constant equaling  $0, \pm 1, \pm 2, \ldots$ 

Table 6 gives the space harmonic indexes (values of  $\nu$ ) corresponding to the odd harmonics of the time variation of the armature reaction MMF. A forward traveling wave is

represented by  $\text{sin}(g_\omega t - \nu \frac{\pi x}{T_p})$ . The velocity of the traveling wave components relative to that of the rotor is equal to the negative time harmonic index (-g) divided by the space harmonic index ( $\nu$ ).

Table 6 Space Harmonic Indexes for Armature Reaction Traveling Waves

g k	0	- 1	+1	-2 +2	- 3	+3
1	-1	5	- 7	11 -13	17	-19
3	- 3	3	- 9	9 -15	15	- 21
5	- 5	1	~11	7 -17	13	- 23
7	- 7	- 1	-13	5 -19	11	- 25
9	- 9	- 3	-15	3 -21	9	- 27
11	-11	- 5	-17	1 -23	7	-29
13	-13	- 7	-19	-1 -25	5	- 31
15	-15	<b>-</b> 9	-21	-3 -27	3	- 33
17	-17	-11	-23_	-5 -29	1_	- 35

#### Comparison

The traveling wave for the rotor MMF is expressed in Equation (25). The harmonic index ( $\nu$ ) in each component is the same for the time and space variation.

The cancellation of two orthogonal functions (Ref 10:188)

$$A \sin(\alpha t) + B \sin(\beta t) = 0$$
 (38)

requires that the magnitudes of  $\alpha$  and  $\beta$  are equal or that both A and B are zero. This applies to the cancellation of armature reaction MMF terms (Equation 36) and rotor MMF terms Equation (25).

If cancellation is to apply to all positions (x) and all times (t), the rotor MMF can only be used in cancellation of armature reaction MMF terms in which g=v. In other words, rotor MMF will only cancel armature reaction MMF that has the same relative velocity (g/v); the velocity of the rotor.

Specification of rotor MMF is not sufficient to control the generator MMF for all of the air gap at all times. The armature reaction MMF produces both space and time variations that are not cancelled. This limited cancellation is more effectively accomplished by the specification of other parameters such as pole arc (see Section II).

Another concern with this approach is that the reluctance function controls the flux density according to Equation (7). Thus, even if a certain MMF harmonic is cancelled, there must be protection from the reintroduction of that harmonic through the variation of the reluctance. Therefore, the use of rotor MMF is not a favored approach in the control of generator harmonics.

### VIII. Reluctance Harmonic Control

This section describes an attempt to control phase voltage harmonics by using the reluctance to control the flux density harmonics.

Neglecting saturation and considering the air gap to be dominant, the reluctance along the air gap is proportional to the air gap distance. In addition, because the air gap rotates with the rotor, the reluctance versus distance has the same shape as the reluctance versus time at a fixed point on the stator. Therefore, although the reluctance requirements may be solved on a time basis, it can be directly related back to the air gap and thus rotor geometry. MMF(x,t) and MMF(t) refer in this section to total MMF.

# Flux Density from MMF

Just as it is the combined voltage of all the conductors connected in series in a coil group which is specified as phase voltage, it is the sum of the flux densities cutting these same conductors that must be controlled. The flux density at each stator slot is determined by the MMF available to force the flux through the reluctance at that point.

The MMF(x,t) around the stator is known. It is the superposition of the MMF(x,t) due to the armature reaction MMF (Section IV) and the MMF  $_{\rm rotor}$  due to the rotor coils (Section V). The time variation MMF(t) at any location along the stator may be obtained by substituting that location's

coordinates into the MMF(x,t) expression. For a given MMF(t), the value of reluctance determines the magnetic flux density. Therefore, for a given MMF(x,t), the desired phase voltage (Section III) may be had by controlling the reluctance.

The reluctance at any location along the stator periphery is also a function of time. Therefore, the total magnetic flux density is:

$$B_{TOT} = \sum_{x=1}^{q} B_x(t) = \sum_{x=1}^{q} \frac{MMF_x(t)}{R_x(t) \cdot Area}$$
 (59)

where

Area is the rotor surface area under a single coil group

 $B_{\mathrm{TOT}}$  is the total magnetic flux density

 $\boldsymbol{B}_{\boldsymbol{X}}(t)$  is the magnetic flux density at slot  $\boldsymbol{x}$ 

 $MMF_{x}(t)$  is the MMF at slot x

 $R_{x}(t)$  is the reluctance at slot x

If, during certain periods  $\boldsymbol{T}_{\nu}$  , the air gap distance under a slot is proportional to the MMF,

$$\mathcal{E}(t) \mid_{T_{y}} = K \cdot MMF \tag{40}$$

where

 ${\tt K}$  is a proportionality constant then the flux density, Equation (8), is a constant over that period.

If the value of the proportionality constant K is changed, the magnitude of the flux density is also changed. The basis for this concept involves a series of these changes combined with careful control of the flux density harmonics.

# Reluctance Specification Concept

The magnetic circuit reluctance function is periodic. The reluctance at any slot is the same function as the reluctance at a previous slot except for a time delay. If the MMF(t) expression for each slot is shifted instead, the sum on the right side of Equation (39) has a common denominator. Using the shifted and summed MMF\*(t) reflected into the first slot, the solution of reluctance versus time will be simplified.

A pulse width current modulation technique for control of line voltage harmonics was presented by Krishnamurthy (Ref 11:1269). His technique is reinterpreted for the time variation of the magnetic circuit. Here permeance is modulated to control the magnetic field.

The resulting flux density variation B(t) will consist of a set of symmetrically shaped increments for each set of harmonic(s) controlled (see Figure 8c). The set of increment centers for the  $n^{th}$  controlled harmonic is given the name  $C_n$  (see Figure 8b) which corresponds to  $B_n$  in Reference 11.

$$B_{v}(C_{n} + \Delta t) = B_{v}(C_{n} - \Delta t)$$
 (42)

and

$$B_{v}(2k\pi + C_{n}) = -B_{v}(2k\pi - C_{n}) = B_{v}[(2k+1)\pi - C_{n}] = -B_{v}[(2k+1)\pi + C_{n}]$$
(43)

where

k is an integer constant equaling 0,  $\pm 1$ ,  $\pm 2$ , ... The product of the permeance and the MMF will be constant in magnitude over the increments, but will change sign every T radians.

The coefficient of the  $n^{\mbox{th}}$  harmonic of the flux density is

$$b_{v} = \frac{8 \text{ B}_{\text{max}}}{v^{\pi}} \sin vd \sum_{n=1}^{c} \sin vC_{n}$$
 (44)

where

- d is the width of an increment (maximum  $\Delta t$ )
- c is the number of harmonics controlled by the increments of concern

When the  $C_n$ 's are chosen such that:

$$\sum_{n=1}^{C} \sin \nu C_n = 0 \tag{45}$$

 $b_{\nu}$  can be made equal to zero for c different harmonics. There will be 4c pulses per  $2\pi$  electrical radians.

## Methodology

The harmonics of the flux density are controlled by respecification of the air gap length under the stator slots during certain periods  $T_n$ . The  $T_n$  periods correspond to the non-zero periods of the modulated wave claculated for no disturbance of the n previously controlled harmonics. The air gap length over each period is such that although there is variation in the MMF, the flux density is constant. The process is accomplished one harmonic at a time with the fundamental completed last.

For the first non-fundamental harmonic to be controlled,  $\nu_1$  , the periods  $T_{\alpha}$  correspond to the entire pole arc.

Equation (8) is rearranged to solve for the length of the air gap over the desired periods.

$$\delta(t) = \frac{\mu MMF(t)_R}{B_v}$$
 (46)

The desired values for the flux density are given by rearrangement of Equation (10).

$$B_{v} = \frac{v_{v}}{v\ell} \tag{47}$$

For the second harmonic to be controlled,  $v_2$ , the air gap is respecified over the periods  $T_1$ . The centers,  $C_{v_1}$ , of those periods are chosen in each fundamental frequency quarter cycle so that Equation (45) is satisfied (c=1). Therefore, there will be no contribution to the  $v_1$  harmonic from the

respecification. The width of the periods is extended to the point that they meet each other or the edge of the rotor pole. The respecification (addition of an increment of permeance over the periods  $T_1$ ) is done so that the  $v_2$  time harmonics of the flux density are the proper value.

Equation (41) is used to calculate the flux density component for  $v_2$  above the pole arc outside of  $T_1$ . The remainder of the necessary flux density,  $\Delta B_{v_1}$ , must come from the period  $T_1$ . The flux density to be added over the periods  $T_1$  must be a constant according to the modulation technique.

Reluctance is proportional to  $\delta$ . If the needed reluctance is  $\delta$ ' and the present reluctance is  $\delta$ , the reluctance to be added is the difference. Returning to the distance domain, the new air gap length must be  $\delta$ '·  $\delta$ /( $\delta$ - $\delta$ '). The respectification for  $\Delta B_{ij}$  becomes

$$\frac{\delta' \cdot \delta}{\delta - \delta'} = \frac{\mu}{\Delta B_{v}} MMF(t)_{R}$$
 (48)

If  $T_n$  extends over the boundaries of previous T, Equation (48) will be valid as long as the proper  $\delta$  versus time is used. Further harmonics are controlled by additional increments of reluctance.

# Example

See Appendix I (Generator Design) for a reference on the generator specifications used in this example.

The third harmonic is chosen as the first to be controlled. The desired flux density is zero. From Equation (46),  $\delta$  is infinite.

 ${\rm T}_1$  is now determined for control of the fifth harmonic (the second to be controlled) without disturbance of the third harmonic. The sum

$$\sum_{n=1}^{1} \sin v_n C_n$$

is zero for  $C_n = \pi/3$ . The centers,  $C_1$ ,  $\pi/3$  radians away from each multiple of  $\pi$  radians are  $\pi/3$ ,  $2\pi/3$ ,  $4\pi/3$ , and  $5\pi/3$ . The width of each increment may be up to  $\pi/3$  before they touch. At this full width, the outside limits of the increments  $T_1$  are  $\pi/6$  to  $5\pi/6$  and  $7\pi/6$  to  $11\pi/6$ . The merged increments are  $2\pi/3$  wide corresponding to the width of the chosen  $2\pi/3$  pole arc. In other words, a  $2\pi/3$  pole arc constant air gap produces no third harmonic. This is consistent with conventional pole arc design (Ref 9:34).

The desired flux density for the fifth harmonic comes from Section III and Equation (47). All of this flux must come from  $T_1$  because the rotor pole arc does not extend past  $T_1$ . From Equation (48) and the fact that  $\delta$  is infinite,  $\delta$ ', (the limit of  $[\delta' \cdot \delta/(\delta - \delta')]$  as  $\delta$  goes to infinity) may be found.

Next,  $T_2$  is determined for control of the next harmonic without disturbance of the third and fifth harmonics. Equation (45) is simultaneously solved for v=3 and v=5 yielding  $C_3=.235^{\circ}$ 

and  $C_5$  = .435°. The centers of the  $B_{\nu_2}$  (t) pulses are .255°, .455°, .566°, .766°, 1.255°, 1.455°, 1.566°, and 1.766° radians. The periods meet and extend to the edge of the pole when their width is .166° radians. The reluctance and flux density waves built with these periods are shown in Figures 8a and 8c. The air gap length over these periods is adjusted to provide the necessary flux density not provided outside of  $T_2$ . The flux density adjustment continues in this manner for other harmonics. The reluctance over the final periods  $T_n$  which affect none of the previously controlled harmonics is adjusted for the fundamental component.

A graphical interpretation helps clarify the process. The periods of non-infinite reluctance, shown in Figure 8b, are calculated as previously described. The air gap length (proportional to reluctance) is obtained during each period by Equation (46). The product of the MMF and the reluctance (the flux density variation) is shown in Figure 8c.

The components of the sine  $a_{\nu}^{*}$  and cosine  $b_{\nu}^{*}$  parts of the each harmonic of the flux density may be calculated from:

$$a_{\chi}^{*} = \frac{1}{\pi} \left\{ \begin{cases} B & \sin \psi_{0} \mathbf{t} \ d_{0} \mathbf{t} \end{cases} \right. \tag{49}$$

$$b_{y}^{*} = \frac{1}{\pi} \begin{cases} B \cos y \omega t \ d\omega t \end{cases}$$
 (50)

The curved bound of the shaded areas in Figure 8d and 8f represent the integrand of Equation (49) where v=3 and 5




Figure 8 Reluctance Harmonic Control Example Wave Shapes

respectively. The curved bound of the shaded areas in Figures 8e and 8f represent the integrand of Equation (50) when  $\nu$ =3 and 5 respectively.

The signed shaded areas in Figures 8d through 8g represent the integrals from Equations (49) and (50). Algebraically, the signed areas of Figures 8d through 8g sum to zero. This illustrates that Equations (49) and (50) are zero for v=3 and for v=5. Thus, the harmonic components are zero for these harmonics because of the chosen reluctance values and periods. The illustration is similiar for other higher harmonics.

### How Many Harmonics

The process as described, approaches the desired flux density wave shape one harmonic at a time. To see the advantage of this approach, consider specification of the reluctance as a composite wave shape.

$$\delta(t) = \frac{\mu \text{ MMF}(t)}{B(t)}$$
 (51)

where

 $\delta(t)$  is a time varying air gap

This requires a specific finite reluctance at all times. When the large air gap between the poles is under the coil group, the reluctance is not variable. This shortcoming affects all the harmonics. Therefore, the chosen method, because the important harmonics can be directly controlled has an advantage.

The number of harmonics which can be controlled is dependent on those chosen and the pole arc. Equation (45) yields  $C_1 = .183\pi$ ,  $C_2 = .344\pi$ , and  $C_3 = .433\pi$ , for control of the 3rd, 5th, and 7th harmonics. If the pole arc length was less than  $.633\pi$ ,  $C_3$  would be at the pole edge and control of these three harmonics could not be achieved. Therefore, the harmonics and the pole arc must be selected consistent with the methodology.

### The Contradiction

The concept of harmonic control appears to be practical once  ${\rm MMF}_R$  (the reflected MMF) is obtained and the control harmonics are selected. However, obtaining  ${\rm MMF}_R$  is not an easy problem.

The proposed shift of MMF at consecutive slots 1 and 2 is

$$MMF_1^*(t) = MMF_2(t-\Delta t)$$
 (52)

where

$$MMF_1^*(t)$$
 is the shifted MMF

The reluctance at one slot is the same function as the reluctance at the previous slot except for a delay of  $\Delta t$ . In other words

$$R_1(t) = R_2(t - \Delta t) \tag{53}$$

An expression for the flux density at the second slot is

$$B_2(t - \Delta t) = \frac{MMF_2(t - \Delta t)}{R_2(t - \Delta t)}$$
 (54)

The shifted MMF and reluctance are then plugged into Equation (54). The contradiction is that the flux density  $B_2(t-\Delta t)$  reflected into the first slot is not synchronized with the flux density at the first slot  $B_1(t)$ . Such a sum makes little sense.

A general solution for a reflected  $B_2(t)$  synchronized with  $B_1(t)$  and with the knowledge of  $MMF_2(t)$ , but not  $R_2(t)$  exceeds the resources of this thesis effort. Therefore, another approach is preferred.

# IX. Incremental Reluctance Specification

This section describes the final method in which the rotor geometry specification is analyzed for control of the generated voltage wave shape. The reluctance of the air gap is specified as the traveling rotor is positioned under consecutive stator slots. Just as in Section VIII, reluctance versus time may also be related to air gap distance versus time and thus to rotor geometry. The specification progresses with time along with the required wave shape.

Therefore, individual harmonic components are not of concern.

#### MMF to Flux Density

The total MMF versus time which was developed in Section VII is a useful starting place for this development. The reluctance must be specified so that the resulting magnetic flux density will be in accordance with the magnetic flux density required, as was discussed in Section III. Air gap dominance, the lack of fringing, and the finite permeance effects are assumed here as they were in Section VIII.

The reluctance at any slots is the same function as the reluctance at the previous slot except for a time delay of At.

$$\Delta t = \frac{G_c}{v_{ang}} \tag{55}$$

where

 $v_{
m ang}^{}$  is the rotor angular velocity  $w_{
m e}^{}$  is the electrical angle between slots

Therefore, the total flux density may be expressed as:

$$B_{TOT}(t) = \sum_{n=1}^{q} B_n(t) = \sum_{n=1}^{q} \frac{MMF_n(t)}{R_1(t - n\Delta t)}$$
(56)

where

n is the individual stator slot number

### Reluctance Specification

When the gap between salient poles is under a slot, the reluctance at that slot may be approximated as infinite. When the rotor turns so that its edge is between the first and second conductor of the relevant coil group, Equation (56) has a non-zero term only for n=1. The desired increment of flux density,  $\Delta B$ , and the available MMF determine the reluctance required while the rotor edge is between slots 1 and 2.

$$R_1(t) = \frac{MMF_1(t)}{\Delta B(t)}$$
 (57)

After a delay of t, that same reluctance will appear under the second slot. The MMF $_2$  at  $(t+\Delta t)$  and the already specified reluctance will determine the flux density at the second slot. The remainder of the desired total flux density must come under the first slot. By using MMF $(t+\Delta t)$  and the residual requirement of reluctance,  $\Delta B$ , in Equation (57), the reluctance at the next increment may be determined. The reluctance specification process is repeated as the rotor progesses under the coil group and is completed once the new

rotor position is  $\boldsymbol{\pi}$  radians from where it was when the specification began.

The specification of the reluctance using this method is very simple. However, insight is required in the choice of the phase voltage wave shape. After the trailing edge of the rotor pole face passes the first slot, the reluctance specification is complete. The phase voltage and the required magnetic flux density must come from the remaining MMF time variation and the reluctance specified to this point.

#### Example

See Appendix I (Generator Design) for a reference on the generator specifications used in this example.

The proof that not just any phase voltage wave shape will work is seen by examination of the example developed so far. Table 5 gives the time variation of the total MMF at each slot for the Figure 5 voltage variation. At  $\omega t = -5\pi/15$ , none of the pole arc is under the phase C coil group. At  $\omega t = -4\pi/15$ , the pole will be under the first conductor of the coil group.

The MMF at  $\omega t = 4\pi/15$  is negative. Additional rotor MMF could be added here in order to ensure a positive magnetic flux density with a realizable reluctance. However, there is another difficulty. The desired magnetic flux density and therefore the desired voltage wave shape is flat between  $zt=-2\pi/15$  and  $\omega t=+3\pi/15$ . At  $\omega t=-2\pi/15$ , a certain combination of reluctances will be under slots 1, 2, and 3 and with the MMFs

(Table 5 entries) will produce the desired magnetic flux density. However, at  $\omega t = -\pi/15$ , the reluctances are exposed to greater MMFs. The new increment under slot 1 also sees a positive MMF. Then the reluctances which provide the correct amount of flux density at  $\omega t = -2\pi/15$  are bound to provide too much at  $\omega t = -\pi/15$ . Therefore, this choice of a phase voltage wave shape is not consistent for wave shape control using only rotor geometry.

## Triangular Phase Voltage Wave Shape Example

The flexibility of the phase voltage wave shape for a required load voltage wave shape as discussed in Section III is valuable. Figure 9 shows a phase voltage wave shape which produces a DC load voltage. Notice that it has an upward ramping voltage as the number of slots with finite reluctances increases and a downward ramping voltage as the number of slots with finite reluctances decreases. In this example, the peak phase voltage equals the load voltage and the pole arc is only \$\pi/3\$ electrical radians. Tables 7, 8, and 9 display the voltage, the magnetic flux density, the current, and the MMF variation at each slot versus time.

The reluctance for this new wave shape is introduced under the first conductor at  $\omega t = -3\pi/30$ . The rotor pole is centered under phase C at  $\omega t = -5\pi/30$ . It is under only one conductor at  $\omega t = 13\pi/30$  as it is leaving the coil group.

Table 10 shows the progressive calculation of the reluctances required for the Figure 9a triangular voltage wave shape. Notice that Table 10 stops with the determination that a negative reluctance is required. A rotor MMF of 1400 ampere-turns was chosen instead of the 533 ampere-turns used previously in order to prevent the calculation of a negative reluctance for the very first entry. This wave shape choice is not appropriate for rotor geometry control.

From the shaded area of Table 9, it is observed that an equation for the magnetic flux density (similar to Equation 39) may be written for each line (at each time increment).

Nine equations with the specified MMF determine the required reluctances. Yet, only five reluctances are variable. The armature current and rotor MMF provide two additional variables. It is clear that design using the method of this section is a form of over-specification. There might be a waveform that fits all of the equations and provides the desired load voltage, but none were found.

Table 7 Normalized Phase Current and Voltage (Triangle Wave Shape) (Figure 9a)

TIME	V	OLTAGE		CUR	RENT	
(wt)	A	В	С	A'	В'	С'
-5π/30	0	1	0	- 1	0	1
-3π/30	0	. 8	2	- 1	.36	.96
-π/30	0	.6	4	- 1	.64	.84
π/30	0	. 4	6	- 1	.84	.64
3π/30	0	. 2	8	- 1	.96	.36
5π/30	0	0	1	- 1	1	0
7π/30	. 2	0	8	96	1	36
9π/30	.4	0	6	84	1	64
11π/30	.6	0	4	64	1	84
13π/30	.8	0	2	34	1	96
15π/30	1	0	0	0	1	- 1
17π/30	.8	2	0	.34	.96	- 1
19π/30	.6	4	0	.64	.84	- 1
21π/30	. 4	6	0	.84	.64	- 1
23π/30	. 2	8	0	.96	.36	- 1
25π/30	0	1	0	1	0	- 1

Table 8 Normalized Armature Reaction MMF Phase C Slots (Triangle Wave Shape)

TIME x ( <sup>ω</sup> t)	π/30	3π/30	5π/30	7π/30	9π/30
-5π/30	-1.80	-1.40	-1.00	60	20
-3π/30	-2.13	-1.74	-1.36	98	59
-π/30	-2.31	-1.98	-1.64	-1.30	97
π/30	-2.35	-2.09	-1.84	-1.58	-1.33
3π/30	-2.25	-2.10	-1.96	-1.82	-1.67
5π/30	-2.00	-2.00	-2.00	-2.00	-2.00
7π/30	-1.67	-1.82	-1.96	-2.10	-2.25
9π/30	-1.33	-1.58	-1.84	-2.10	-2.35
$11\pi/30$	97	-1.30	-1.64	-1.98	-2.31
13π/30	57	96	-1.34	-1.72	-2.11
$15\pi/30$	20	60	-1.00	-1.40	-1.80
17π/30	.18	22	62	-1.02	-1.42
$19\pi/30$	.60	.20	20	60	-1.00
$21\pi/30$	1.00	.60	.20	20	60
23π/30	1.40	1.00	.60	20	20
$25\pi/30$	1.80	1.40	1.00	.60	.20

Table 9 Total MMF at Phase C Slots (Triangle Wave Shape)

TIME X	-/30	3 m/30	5 π/30	7 m/30	9 π/30
-5~/30	-1129.59	-878.57	-627.55	-376.53	-125.51
-37/30	63.32	-1091.94	-853.47	-615.00	-370.25
-7/30	-49.64	157.45	-1029.18	-815.81	-608.72
~ / 30	-74,74	88.42	245.31	-991.53	-834.64
3~/30	- 11.99	82.14	170.00	257.86	-1048.00
5=/30	144.90	144.90	144.90	144.90	144.90
75/30	-1048.01	257.86	170.00	82.14	-11.99
9π/30	-834.04	-991.53	245.31	82.14	-74.74
11π/30	-608.72	-815.81	-1029.18	157.45	-49.64
13π/30	-367.70	-602.45	-840.92	-1079.39	75.87
15~/30	-125.51	-376.53	-627.55	-878.57	-1129.59
17-730	112.96	-138.06	-389.08	-640.10	-891.12
19=/30	3~6.53	125.51	-125.51	-376.53	-627.55
21=/3.1	627.55	376.53	125.51	-125.51	-376.53
25=/50	878.57	627.55	376.53	125.51	-125.51
25*/50	1129.59	878.57	627.55	376.53	125.51

Calculation of Incremental Reluctances (Triangle Wave Shape)

5 4 5 2 000		12		TOTS IV	,		ATTAINE	ATAINED B AT SLOT	SLoT		B at	R at
215.4	 ji.	c i			ıv	C1	tG	<b>-</b> †	in	TOTAL	1	
258	Ġ.	-		,	-	000.	}		000	ł	1	8
517 237.4	(1)	-		S	8	one.						245.42
7 5 5 8 6 245 4	Pr4	10. C I			3	6.41		000.				598.59
25 157. 428 167. 4 308.6 245. 4 11.28 . 805 . 505	1	S. 37. 17.	4.545	u.	-	.222	,					167.44
32 12.8 167.4 338.6 245.4 11.28 .865 .565				13	-	154.				1.96.1	1.59	12.84
	( ) ( ) ( )	У.	167.4	338.0	143.4	11.28			065.	15.104	-11.812	
									-			




Figure 9 Triangle Phase Voltage and Current Wave Shapes

#### X. Other Magnetic Effects

This section discusses the effects of flux leakage, flux fringing, and flux saturation on the desired generated voltage wave shape. Finite Element analysis, an important analytical tool, is introduced as a computer-aided design method used in fine tuning and checking the generator design. One example of a magnetic finite element analysis program is introduced.

#### Introduction

All of the procedures, methods, and examples in this thesis effort assume zero flux leakage, no flux fringing, and no saturation in the generator's magnetic structure. These are important assumptions because calculating flux leakage, flux fringing, and saturation require a knowledge of the complete magnetic structure; something that is not available in the initial design stages. Generator design is by nature an iterative process due to these three problems.

When a generator is designed for a specific load, the system inductance is an important specification. The system inductance depends on the load inductance, the transmission line inductance, and also the generator inductance. The generator inductance can easily be the most significant of the three inductances. The generator inductance depends

on the geometry of the magnetic circuit. Designing the magnetic circuit, however, depends on a knowledge of the system inductance. Normally, a "first cut" design is made from which a "first cut" system inductance can be calculated. Using this inductance, a "second cut" design is made from which a "second cut" system inductance can be calculated. This process continues until it converges on a final design.

This thesis effort is concerned only with the "first cut" design. The rest of the design procedure is left for further study.

#### Leakage Flux

In the generator, the rotor magnetic flux is generated in the rotor coils. The flux travels through the rotor poles and into the stator magnetic structure cutting the armature coils and thus, generating the output voltage.

In a salient pole generator, there is a large air gap between two adjacent poles. The magnetic reluctance is very high, but does have a finite value. Since there is an MMF drop between two adjacent poles, there will be magnetic flux crossing the gap between the poles bypassing the stator. All of this leakage flux which bypasses the stator does not have a significant impact on the shape of the desired output voltage waveform, although it does increase the generator inductance,  $X_{\mathfrak{g}}$ . To compensate for

this leakage flux, all the designer needs to do is increase the number of ampere turns in the rotor coils.

#### Fringing Flux

Another important assumption made in this thesis effort is that all the flux generated in the rotor passes through the air gap, past the armature coils and into the stator core in a totally radial direction. This is an important "first cut" assumption and can be corrected for in further design iterations.

In a realistic generator, the majority of the magnetic flux does go in the radial direction. However, there is a significant amount of flux which does not. This flux crosses the air gap in directions defined by the magnetic flux density vector  $\vec{B}$  causing a distortion of the desired output voltage wave shape. The flux can also short cut across several armature slots instead of going straight through.

Accounting and correcting for this fringing flux so that the correct flux links the armature coils is no simple matter. Where and how the flux fringes depends on the shape of the generator's magnetic structure. The correction for the flux fringing is therefore an iterative design process.

#### Magnetic Saturation

The last important assumption made in this thesis effort is that the relationship between the MMF, the reluctance of the magnetic material, and the resultant flux density in the magnetic material is linear. This last assumption said another way means that the analysis in this thesis effort ignores the effects of saturation of the magnetic material.

In a realistic generator, this relationship is definitely non-linear. When the MMF dropped across the magnetic structure is a given value, a certain amount of magnetic flux will "flow" through the material. As the MMF increases, the flux flowing through the material also tends to increase. However, at high enough values of flux density, the magnetic material saturates and more and more MMF is required for smaller increases in the flux.

As was true for the flux fringing, the locations and the severity of the flux saturation are determined by the structure of the magnetic circuit. Compensating for this problem can also be an iterative design procedure.

#### Finite Element Analysis

The calculations involved in designing a generator can be exceedingly complex and cumbersome. This fact makes the digital computer a welcome design aid. One particular procedure ideally suited for computer-aided design is Finite Element analysis.

In Finite Element analysis, a cross section of the generator is taken perpendicular to the axle. Then the assumption is made that any leakage flux or fringing flux is in the plane of the cross section. That is, there is no leakage flux or fringing flux between any two "adjacent, infinitely thin" cross sections. The two dimensional cross section is then divided up into triangular finite elements. Each element is restricted to one particular type of material (steel, air, insulation, ...). During the computations, each triangular finite element is considered to have a constant magnetic flux density over the entire element. See (Ref 8) and (Ref 13) for further information on the Finite Element method.

MAGNETIC is a computer program that uses the Finite Element analysis technique (Ref 4) to analyze magnetic structures. MAGNETIC computes the magnetic fields, induced currents and losses, and the forces of a magnetic device that has been represented as a collection of finite elements.

"MAGNETIC aids the design of magnetic devices because accurate prediction of devices performance usually requires knowledge of the magnetic field. MAGNETIC is a means of calculating the field that allows for fringing, saturation, permanent magnets, and complicated shapes. Because the program includes non-linear B-H curves and computes inductances, forces, and eddy current losses, it can help the designer to minimize the materials used in a device and maximize its efficiency." (Ref 4:I1)

Two problems in generator design, flux fringing and saturation, force the design procedure to be iterative.

MAGNETIC can be a welcome aid in correcting for flux fringing and saturation as well as flux leakage. After the designer has completed the "first cut" design, the design can be analyzed by MAGNETIC. MAGNETIC shows through its output, where and to what extent flux fringing, saturation, and flux leakage are occurring. With this information, the designer is able to take corrective action and come up with a "second cut" design. This procedure continues until an acceptable design is obtained.

In addition to tabular listings of the various output parameters, MAGNETIC produces a Mesh plot and a Flux plot. The Mesh plot portrays the selected generator cross section showing all the triangular finite elements. The Flux plot shows the lines of magnetic flux in the generator cross section. Figure 10 is the Mesh plot for the sample generator (Reference Appendix I). The Flux plot of the sample generator is not shown because that portion of MAGNETIC currently does not work.




Figure 10 Sample Generator Mesh Plot

#### XI. Conclusions and Recommendations

#### Conclusions

The purpose of this thesis effort was to investigate the use of rotor geometry as a specification in the control of generator voltage and flux density harmonics. It was found that armature reaction MMF could be expressed as an infinite set of traveling waves with an infinite set of velocities (Section IV) and (Equation 23). Because the rotor MMF has only the velocity of the rotor, it cannot cancel armature reaction everywhere in the generator throughout all time (Section VII).

Rotor geometry was put to use in a limited control of flux density harmonics at the stator slots. The reflection of the MMFs present at all of the slots of a coil group into a single slot allows the possible calculation of an appropriate rotor geometry. This reflection turned out to exceed the resources of this thesis effort and was not accomplished (Section VIII).

Specifying the air gap reluctance incrementally as the rotor moves under successive stator slots was also tried as a means of harmonic control. This method was unworkable for all wave shapes chosen because it produced negative MMF requirements and conflicting geometry specifications.

#### Recommendations

The control of flux density is an important consideration when working to improve generator efficiency and performance. Because of the potential that flux density control has, several recommendations for further study are presented.

Before any hardware is fabricated, it is recommended that the designer calculate the benefits due to the flux density control design. Knowing that energy is conserved between the input and the output of the generator, the designer will be able to calculate the design's value.

A recommended approach for reduction of losses is to investigate flux density control at the damper hars instead of the stator windings. This investigation however, will not control the generator output harmonics.

A different approach might be to use stator geometry as a design specification in harmonic control. This will not control the MMF at all time and all space by itself, but may provide easier control of the harmonics at a given location.

The method in Section VII could be further investigated if a method were derived for the division of one infinite series with progressive harmonic arguments by another such series. The Section VIII approach could be further investigated in terms of a general wave shape

(see the heading "The Contradiction" in Section VIII).

Either method might provide a workable wave shape or prove that the rotor geometry concept is in general impossible.

The general requirement for phase voltage wave shapes that produce a DC output from a three phase full wave bridge rectifier is:

Voltage (t) + Voltage 
$$(\frac{T}{2} + t) = a \text{ constant}$$
 (58)

where

Voltage (t)

is the wave shape during the first half of the period in which voltage is applied to the load

Voltage  $(\frac{T_a}{2} + t)$  is the wave shape during the second half of the period in which voltage is applied to the load

Ta is the period in which the phase voltage is applied to the load

t is the time variable within the first half of the period  $\Upsilon_{\mathbf{a}}$ 

This could be a start in the exploration for a general phase voltage wave shape.

An additional recommendation is to investigate the shaping of rotor MMF using electronic control of the current in the rotor coils. This will aid in the shaping of the required flux density harmonics in the air gap.

. . . .

The final recommendation is to include the flux fringing, flux leakage, and magnetic saturation problems in the calculation (only if the calculations are successful without these three problems) for the desired phase voltage wave shape. It should be recognized that the problem will now be iterative and Finite Element analysis (Section X) will be helpful.

## Bibliography

- 1. Adams, Arlon. <u>Electromagnetics for Engineers</u>. New York: Ronald Press Company, 1971.
- 2. Air Force Extension Course Institute. Course 54350 Cenerator and Control Equipment. Study Reference Guide Volume 2. Gunter AFR, Alabama, Air Training Command, April 1969. (54350-02-0869)
- 3. Appleyard, R. E. and William L. Ringland. "Alternating-Current Generators" in Standard Handbook for Electrical Engineers (Tenth Edition). Editor-In-Chief: Donald G. Fink. New York: McGraw-Hill, Inc., 1968.
- 4. Brauer, John R. <u>Magnetic Handbook</u>. Milwaukee, Wisconsin: A. O. Smith Corporation, May 1979.
- 5. Brockhurst, F. C., Professor of Electrical Engineering. Lecture materials distributed in EE 6.07, Electromechanical Components Design. School of Engineering, Air Force Institute of Technology, Wright-Patterson AFB, Ohio, 1980.
- 6. Erickson, William. Electrical Engineering Theory and Practice (Second Edition). New York: John Wiley & Sons, Inc., 1959.
- 7. Franklin, Paul W. Theory of the Three Phase Salient Pole Type Generator Part I. Presented at the IEEE Winter Power Meeting. New York: January 30, 1972.
- 8. Huebner, Kenneth H. The Finite Element Method for Engineers. New York: John Wiley & Sons, Inc., 1975.
- 9. Jain, Giand Chand. <u>Design, Operation, & Testing of Synchronous Machines</u>. Bombay, India: Asia Publishing House, 1966.
- 10. Kreysig, Erwin. Advanced Engineering Mathematics (Fourth Edition). New York: John Wiley & Sons, Inc., 1979.
- 11. Krishnamurthy, K. A. "AC DC and AC AC Converter Control with Selective Reduction of Line Harmonics," IEE Proceedings, 125 (11): 1269-1270 (November 1978).

- 12. Shiling, W. J. "Exciter Armature Reaction and Excitation Requirements in a Brushless Rotating Rectifier Aircraft Generator," AIEE Transactions on Applications and Industry, 79 Part 2: 394-402 (1960).
- 13. Shugar, Theodore A. Mathematical Theory of the Finite Element Method Some Introductory Aspects. TN number N-1552; Program numbers ZR000-01-169. Civil Engineering Laboratory, Naval Construction Battalion Center, Port Hueneme, California, April 1979. (ADA070861)
- 14. Spiegel, M. R. Schaum's Outline of Theory and Problems of Fourier Analysis with Applications to Boundary Value Problems. New York: McGraw-Hill, Inc., 1974.

Appendix I Sample Generator

Specifications and Dimensions for the Sample Generator

## Appendix I Sample Generator

The development of the rotor geometry modification example in this thesis requires a constant air gap, salient pole, synchronous generator to begin the investigation.


The generator selected is basically the one designed for the final exam in Air Force Institute of Technology course EE 6.07 (Electromagnetic Components Design, Spring, 1980).

A few modifications are made due to thesis requirements.

The design procedure for the sample generator is not presented. Specifications for the sample generator are presented in Table 11. A cross sectional drawing (perpendicular to the axle) of the generator is presented in Figure 11.

The design modifications developed in this thesis apply equally as well to any salient pole, synchronous generator as they do in the generator used to begin the investigation.

Notice that the generator design is in inches. All units shown in this appendix are converted to the MKS system for use in the body of this thesis.



#### Table 11

#### Sample Generator Dimensions and Specifications

## Machine Specifications

WYE connected three phase output 460 volts RMS line to neutral phase voltage 72.464 amperes RMS phase current Load power: 100 kilowatts Frequency: 400 hertz No rotor or stator vents Straight slot stator design 60 slots 4 poles 0.015 inch constant air gap over the poles Synchronous speed: 12000 revolutions per minute Rotor tip speed: 393 feet per second Rotor MMF: 533 ampere turns per pole Maximum flux density: 1 Tesla Pole arc: 60 mechanical degrees,  $\alpha_p = 0.667$ Rotor length: 25.347 inches Trancor "T" steel with 0.007 inch laminations Synchronous salient pole design

#### Winding Specifications

Six internally generated phases, m = 6 Armature conductors have no skew,  $K_{\text{SV}} = 1.0$  q = 5 One series current path per output phase Full pitch stator winding,  $\text{W/T}_{\text{p}} = 1.0$ ,  $K_{\text{pV}} = +1.0$  Two layer lap design 0.107 by 0.107 inch square conductors 15000 amperes per square inch maximum current density 80 volts per mil minimum insulation thickness  $T_{\text{p}} = 15 \text{ slots}$ 

# Assumptions (for "first cut" calculations)

Zero flux leakage Zero leakage reactance PF = 1.0




Figure 11 Cross Section of the Sample Generator (Specifications and Dimensions)

## Appendix II RGRID and TRIA Card Generation

Computer Program to Generate RGRID and TRIA Cards Required by MAGNETIC (Ref 4) for the Air Gap and Pole Shoe Regions of the Sample Generator (Appendix I)


#### Appendix II RGRID and TRIA Card Generation

The following program listing generates the RGRID and TRIA cards required by MAGNETIC (Ref 4) for the air gap and pole shoe regions of the sample generator (Appendix I).

Refer to Figure 12 and to the program listing for an explanation of how to use the program. Basically, to modify the program for another generator, the following must be accomplished:

- 1) Fill in the appropriate numbers in the three data statements.
- 2) Calculate values for the theta and radial coordinates for the points A, B, C, and D.
- 3) Write a statement function that describes the surface of the pole shoe.

The internal program structure is not discussed because it is not important for the program's use.



Cross Section of the Sample Generator (RGRID and TRIA Cards) Figure 12

```
PROGRAM THESIS: (INPUT, OUTPUT, PUNCH, TAPES=OUTPUT, TAPE7=PUNCH)
 THIS PROGRAM GENERATES ONLY THE AIR SAP AND POLE SHOE RGRID
 AND TRIA CAPDS REQUIRED BY THE PROGRAM MAGNETIC (REF &) FOR
 THE SAMPLE GENERATOR
  VARIABLE DIMENSIONS
   ANG - ANGLE FOR INDIVIDUAL RERID CARDS
   KEY - KEY=1 DESIGNATES A TRIA IS AIR, KEY=0 DESIGNATES STEEL
   LMG - LNG+1 = FIRST SRID NUMBER ASSIGNED
   ENS - LNS+1 = LOWEST GRID NUMBER ON THE STATOF AIR GEP FOUNDARY
   LNT - LNT+1 = FIRST TRIA NUMBER ASSIGNED
   LPG - LPG+1 = FIFST GRID NUMBER ON THE RB ARD
   NE
      - NUMBER OF FGRID POINTS ON SEGMENT KE (INCLUDES THE ENDS)
   NFA - NUMBER OF PGRID POINTS ON SEGMENT KFA (INCLUDES THE ENDS)
   MES - NUMBER OF AGRID POINTS ON SEGMENT KER (INCLUDES THE ENDS)
   PG - RGRID NUMBER TO BE PUNCHED
   NG1 - NUMBER OF AGRID POINTS ON SEGMENT KG1 (INCLUDES THE ENDS)
   MP - NUMBER OF EGRID POINTS ON SEGMENT KP (IMCLUDES THE ENDS)
   MPA - NUMBER OF EGRID POINTS ON SEGMENT KPA (INCLUDES THE ENDS)
   MPR - NUMBER OF EGRID POINTS ON SEGMENT KPP (INCLUDES THE ENDS)
   NT - TRIA NUMBER TO BE PUNCHED
   PI - CONSTANT 3.1415926535 ...
   RAD - RADIAL DISTANCE TO THE POLE FACE SURFACE
   761 - RADIAL DISTANCE TO THE MIDDLE OF THE AIR GAP
C
   XAB, XCC, XCD, XT, XY, XZ, AND YCC ARE USED TO CALCULATE
   THE COORDINATES FOR THE POINTS A, B, C, AND D.
C
   PA, RB, RC, AND RD ARE THE RADIAL COORDINATES OF A, P, C, AND D.
   TA, TB, TC, AND TO ARE THE THETA COORDINATES OF A, B, C, AND D.
 THE FOLLOWING VARIABLES ARE USED INTERNALLY IN THE PROGRAM ONLY:
                                        BARKC
         DKTR
                   DNFP
                             DNFPA
                                                  DNGFM2
                                                            DNSG1
                   KR
                                        VFAM1
         Ī
                              KT
                                                  NFBM1
                                                            NFM1
                   NPAM1
         NG 1M1
                              NP841
                                        NPM1
  THE FOLLOWING ARE PESIGNATED LINE SEGMENTS - SEE FIGURE 12
         ΚF
                   KFA
                              KFB
                                        KG1
                                                  KP
                                                             KPA
         KPB
  SUBROUTINES FERUIRED:
      TRIA1 - PUNCHES TRIA CARDS FOR TYPE 1 FINITE ELEMENTS
      TRIA2 - FUNCHES TRIA CARDS FOR TYPE 2 FINITE ELEMENTS
   SEE TRIA1 AND THIA2 FOR FURTHER EXPLANATION.
      DOUBLE PRECISION TA, TB, TC, TD, RA, RB, RC, RD
      DOUBLE PRECISION ANG, RAD, PI
      DOUBLE PRECISION XY, XZ, XT, XCC, YCC, XCD, XAB
```

```
DATA NFA,NF,NFP,NPA,NP,NPB,NG1,NS /11,41,11,6,23,6,61,61/
      DATA LNG, LNT, LPG, LNS /275,405,28,214/
      DATA RG1 /3.7575/
O THIS STATEMENT FUNCTION REPRESENTS THE SUFFACE OF THE POLE
O SHOE. IT IS THE DISTANCE VERSUS X (THE DRIGIN IS IN THE
C CENTER OF THE POLE) ABOVE THE RE ARC.
                                         IN THIS CASE, A CONSTANT
S ATP GAP HAS BEEN SPECIFIED. THE ONLY RESTRICTION IS THAT THE
3 POLE FACE MAY NOT HAVE ANY PORTIONS THAT ARE CONSTANT THETA
C LINES.
      SURF (THETA) = 1.212257 075 47377 357 17547 5236DC
G
1815 FORMAT ("1")
 1010 FORMAT(" ","RGDID",5X,13,2(5X,F15.10))
 1 125 FORMAT ("RGRID", 5X, 13, 2(5X, F15.10))
 GIVEN THE EQUATION FOR THE POLE SHOE SURFACE, CALCULATE THE
  COORDINATES FOR THE PCINTS A, B, C, AND D.
      THE CONSTRAINTS ARE:
          THE ARC LENGTH BETWEEN POINTS A AND B MUST BE 60
          MECHANICAL DEGREES.
          THE LINE SEGMENTS AB AND DO MUST BE PARALLEL TO A
          LINE THROUGH THE CENTER OF THE GENERATUR DIVIDING
          THE POLE IN HALF.
      PI=3.141592653689793283462643383279503
      TA=75.000*PI/183.003
      TO=15.10 *PI/189.000
      XY=DSORT(0.50:+3.3600+3.3600)
      X7=DSORT(4.5D(*1.3200*1.3200)
      XT=DSQRT(6.500+0.19500+6.19500)
      XCC=XY+X7+XT
      YCC=X7-XT
      RC=DSORT((XCC*XCC)+(YCC*YCC))
      R7=90
      R4=SURF(TA)+RB
      RD=SURF(TD) +RB
      XAB=RA*DSIN(36.003*PI/180.003)
      TB=(45.CDU*FI/185.CDU)+DASIN(XA9/RB)
      XCD=F0*DSIN(30.005*PI/180.001)
      TC=(45.600*PI/180.000)-DASIN(XCD/RC)
C
      WRITE (6,1906)
2 PUNCH THE RGRID CARDS.
C RERID POINTS ARE TO BE EQUALLY SPACED ON GIVEN SEGMENTS.
3 REMOVE THE C IN COLUMN 1 PRIOR TO ALL WRITE(7, ... STATEMENTS
```

```
O IF PUNCHED CARD OUTPUT IS DESIRED.
 PUNCH REGID CAFDS FOR SEGMENT KPR - ONLY THE RIGHTHAND END POINT
      NG=LPG
      NORM1=NPF-1
      00
                     1=1,NP8M1
             1:
      ANG= (TO/NPPM1) (I-1) + (180.0) /PI)
      N3=NG+1
      WRITE (6,1-10) MG, RB, ANG
      WRITE (7, 1u2() NG, RB, ANG
   10 CONTINUE
  PUNCH RERID CARDS FOR SEGMENT KP - DALY THE RIGHTHAND END POINT
      NPM1=NP-1
                     I=1,NPM1
      20
             25
      ANG=(TC+(((TB-TC)/NPM1)*(I-1)))*(180.402/PJ)
      NG=NS+1
      WRITE (5,101c) NG, RB, ANG
      WRITE (7, 102() NG, RE, ANG
   27 CONTINUE
C PUNCH RGPID CARDS FOR SEGMENT KPA - BOTH END POINTS
      NPAM1=NPA-1
      00
              3(
                     J=1,NPA
      ANG=(T9+((((PI/2.800)-TB)/NPAM1)+(I-1)))*(180.100/PI)
      NG=NG+1
      WRITE (5,1010) NG, RB, ANG
      WRITE (7, 1,21) NG, RB, ANG
   39 CONTINUE
  PUNCH RERID CARDS FOR SEGMENT MEB - ONLY THE RIGHTHAND END POINT
      NG=LNG
      NF3M1=NF8-1
                     1=1,NFBM1
      DO
             45
      ANG= (TO/NFBM1) (I-1) + (180.00./PI)
      NG=NG+1
      WRITE(5,1010) NG, RD, ANG
      WRITE (7,1027) NG, RD, ANG
   40 CONTINUE
C PUNCH RERID CARDS FOR SEGMENT KF - BOTH END POINTS
      NF41= NF-1
                     I=1, NFM1
              56
      חח
      ANG=(TD+(((TA-TD)/NFM1)*(I-1)))*(133.003/PI)
      RAD=SURF (ANG)+5B
```

```
NG=NG+1
      WRITE(6,1,15) NG, RAD, ANG
      WRITE (7, 1021) NG, RAD, ANG
C
   FF CONTINUE
 PUNCH ROWID CANDS FOR SEGMENT KEA - BOTH END POINTS
      NEAM1 = NEA -1
             ٤,
      nn
                     I=1,NFA
      ANG=(TA+((((PI/2. 00)-TA)/NFAM1)*(I-1)))*(18:. 05/PI)
      NG=NG+1
      WRITE (5,1.1') NG, RA, ANG
      WRITE (7,1021) NG, RA, ANG
   FC CONTINUE
C PUNCH RGFID CARDS FOR SEGMENT KG1 - BOTH END FOINTS
      NG141=NG1-1
             7:
                     I=1.NG1
      ANG=(((PI/2..D:)/NG1M1)*(I-1))*(191..D*/PI)
      NG=NG+1
      WRITE (5,1310) NG, RG1, ANG
      WRITE (7,1,2°) MG, RG1, ANG
   75 CONTINUE
CIALL OF THE AGRID CARDS ARE NOW PUNCHED
C PROCEED TO PUNCH THE TRIA CARDS
C REMOVE THE C IN COLUMN 1 PRIOR TO ALL WRITE(7, ... STATEMENTS
O IF PUNCHED CUTPUT IS DESIRED.
C PUNCH TRIA CAPDS FOR REGION T1 (PETWEEN THE QUADRATURE AXIS
C AND THE RIGHT SIDE OF THE POLE SHOE
      KEY=1
      NT=LNT
      KT=1
      K9=1
      DNFPB=FLOAT (NFB) /FLOAT (NPB)
   8" DKT9=FLOAT (KT) /FLOAT (KP)
                              GO TO 98
      IF (DKTB.GT.DNFPR)
      IF (KT.EO.NFB)
                          GO TO 100
      CALL TRIA1 (KT, KB, LNG, LPG, NT, KEY)
      GO TO ST
   OD CALL TRIAZ (KT, KB, LNG, LPG, NT, KEY)
      GO TO 82
  PUNCH TRIA CARDS FOR REGION T2. (THE POLE SHDE)
```

```
1 C KEY=
     LNG=LNG+NFB-1
     LPG=LPG+NPB-1
     KT=1
     K3=1
     O JEP=FLOAT (NE) /FLOAT (NP)
 11 TKT3=FLOAT(KT)/FLOAT(KP)
     IF (OKTR.GT.DNFP)
                           GO TO 12
     IF (KT.EO.NF)
                     GO TO 131
     CALL TRIFT (KT, KR, LNG, LPG, NT, KEY)
     GO TO 111
 12' CALL TRIAZ (KT, KB, LNG, LPG, NT, KEY)
     GO TO 11"
PUNCH TRIA CARDS FOR REGION T3 (BETWEEN THE DUADFATURE AXIS
AND THE LEFT SIDE OF THE POLE SHOP)
170 KEY=1
    LNG=LNG+NF-1
     LPG=LPG+NP-1
     K7=1
     K7=1
    DNFPA = FLOAT (NFA) / FLOAT (NPA)
1/ " DKT3=FLOAT(KT)/FLCAT(KB)
     IF (DKTB.GT.DNFPA)
                           GO TO 150
                       GO TO 160
     IF (KT.EQ.NFA)
     CALL TRIAL (KT, KB, LNG, LPG, NT, KEY)
     GO TO 141
150 CALL TRIA2 (KT,KB,LNG,LPG,NT,KEY)
    60 TO 14'
PUNCH TRIA CARDS FOR REGION T4. (LOWER HALF OF THE LIR GAP)
150 KEY=1
    LNG=LNG+NFA
    LPG=LNG-NFA-NF-NF8+2
    KT=1
    K3=1
    DNGFM2=FLOAT (NG1) /FLOAT (NFA+NF+NFB-2)
177 DKT3=FLOAT(KT)/FLOAT(KB)
    IF (DKTB.GT.DNGFM2)
                             GO TO 180
    IF (KT.EC.NG1)
                       GO TO 193
    CALL TRIF1 (KT, KR, LNG, LPG, NT, KEY)
    GO TO 170
183 CALL TRIA2 (KT, KB, LNG, LPG, NT, KEY)
    GO TO 175
PUNCH TRIA CARDS FOR REGION T5. (UPPER HALF OF THE AIR GAP)
198 KEY=1
```

```
LNG=LNS
LPG=LFG+(NFA+NF+NFB=2)
KT=1
KR=1
DNGG1=FLOAT(NS)/FLOAT(NG1)
Z OKT3=FLOAT(KT)/FLOAT(KR)
IF (DKTB.GT.DNGG1)
GO TO Z1
IF (KT.EO.NS)
GO TO ZZ
CALL TRIA1 (KT,K7,LNG,LPG,NT,KEY)
GO TO ZL
ZT CALL TRIA2 (KT,KR,LNG,LPG,NT,KEY)
GO TO ZL
ZT STOP
END
```

```
O THIS SUBPOUTINE PUNCHES TRIA CARDS FOR TYPE 1 FINITE ELEMENTS.
O SEE THESTS1 FOR AN EXPLANATION OF ALL VARIABLES.
O DEMONT THE C IN COLUMN 1 PRICE TO ALL WRITE(7, ...STATEMENTS
S IF PUNCHED OUTPUT IS DESIRED.
3 TYPE 1 FINITE ELEVENTS ARE TRIANGLES WITH DOWNWARD POINTING
C APEXES.
      SUBROUTINE TRIAL (KT, KR, LNG, LPG, NT, KEY)
      N2=KT +LNG
      N1=N2+1
      N3=K3+LP6
      KT=KT+1
      NT = NT +1
      IF (KEY.EQ.1)
                         GO TO 22
      WRITE(6,1.11) NT, N1, N2, N3
 WRITE (7,1011) NT, N1, N2, N3
101 FORMAT (" ", "TRIA", 4(5X, I3))
 1011 FORMAT ("TRÍA", 4 (5X, 13))
      RETURN
   2 WRITE (6,1021) NT, N1, N2, N3
      WRITE (7,1021) NT, N1, N2, N3
1023 FORMAT(" ","TRIA",4(5X,13),5X,"AIR")
 1021 FORMAT ("TRÍA", 6 (EX, 13), 5X, "4 IR")
      RETURN
      END
```

```
O THIS SUPPOUTINE PUNCHES TRIA CARDS FOR TYPE 2 FINITE ELEMENTS.
O STE THESIST FOR AN EXPLANATION OF ALL VARIABLES.
O PERGYT THE C IN OCLUMN 1 PRIOR TO ALL WRITE(?, ...CTATEMENTS
DIE PUNCHED CUTPUT IS DESIRED.
2 TYPE 2 FINITE ELEMENTS ARE TRIANGLES WITH UPWARD POINTING
O AFFYER.
      SURROUTINE TRIAZ (KT, KB, LNG, LPG, NT, KEY)
      N1=KT+LNG
      N2=KB+LPG
      N7=N2+1
      K9=K9+1
      NT=NT+1
      IF (KEY.FO.1)
                         GO TO 28
      WRITE(5,1.11) NT, N1, N2, N3
      WRITE (7,1311) NT, N1, N2, N3
131 FORMAT(" ","TRIA",4(5X,13))
1011 FORMAT ("TRIA", 4 (5x, 13))
      RETURN
   20 WRITE (5,1120) NT, N1, N2, N3
WRITE(7,1,21) NT,N1,N2,N3
1725 FOPMAT(" ","TF1A",4(5X,13),5X,"AIR")
1021 FORMAT ("TPIA", F(FX, I3), 5X, "AIR")
      RETUPN
      ENU
```

RGRID	25	3.5377 +29 245	J_n3%3666955
RGRIT	3:	7.537 120245	2.5989233584
RGPID	31	3.1 377 (23 265	5.1978467158
RGRID	32	3.5377429245	7.7907710751
RSRTO	77	7, 5377-242.9	13996534375
K GP 17	34	3.1377 292 7	12.994(157913
RGRI)	3.0	3, 5 277 27 2 15	1 : . 55. 197 1035
RGRID	7.0	3.5377425245	18.8137773772
RGF])	7.	3.1317-202-5	21./233576555
RGRI)	<del>Z</del> a	3.53.7.272-6	26329379692
RGRID	73	3.53.7.232.5	27.5425182511
RGRID	L, ?	3.5377421245	37.452(935418
RGRID	41	3.53/7,292.5	33.361676837+
RGRID	42	7.5377:23272	36.2712591251
RGRID	1.7	3.53/7/22295	39.18:8394167
RGRID	4.4	3.5377423245	42.6904197684
RGRID	17	3.1 3/7 +29 215	45.6360696663
RGRID	L.E.	7.6377427275	+7.9395352915
RGRIT	4.7	3.53774292.5	51.8191665833
RGRID	49	3.5377429245	53.72874 08743
RGRID	្តី ខ្លួំ	3.1 377-232 15	56.c333211655
RGRID	5.5	7.53771292+5	59.5479.14592
RGRID	F1	3.5377.429.245	52.4574817493
RGRID	25	3.5377423245	05.3670626415
RGRID	5 5 7	3.5.377.292.5	63.27661 23332
RGRID	54	3 • 5 37 7 • 29 2 • 5	71.1062225258
RGRID	55 55	3.5377.4292.5	74.6953929164
RGRID	E.	3.5377429245	77.:053832081
RGRID	r.	3.53774232.5	79.6843065565
RGRID	FB	3.5377.292.5	32.2332293249
RGR10	50	3.5377429245	84 . 86215 32832
RGRID	ŔĊ.	3.5377429245	87.4010766415
RGRID	51	3.5377429245	91.00000000000
RGRID	275	3.75(16) 11)	0.3503006533
RGRID	277	3.7500000000	1.5000000000
RGRID	279	3.75(201/220	3.00000000000
RGRID	279	3.75001000100	4.50000000000
RGRID	280	3.7500000000	6.0000000000
RGRID	281	3.7510000000	7.50000.0000
RGRID	282	3.750000000	9.36666669999
RGRID	283	3.7553333330	10.50000000000
RGRID	284	3.7500000 300	12.0035090000
RGRID	285	3.7500000000	13.500000000000
RGRID	286	3.750010.0.0	15.000000000000
RGRID	287	3.7500000000	16.5000000000
RGRID	288	3.756013710	18.00000000000
RGRID	289	3.75.000.000	19.5000000000
RGRID	291	3.7503.01.030	21.00000000000
RGRID	291	3.7590000 100	22.500000000000
RGRID	232	3.75000000000	24.639.030369
VAKTO	£ 7£	21. 7/ 1940.204	C-4400300000303

RGRID	293	3.7560001111	25.50000000000
RGRID	Sàr	3.75.0000000	27.0000000000
RGRIC	205	3.750 )/30 108	28.50500000000
RGRID	295	7.7500000.000	36.0000100011
RGRID	2a-	3.75.0:0.900	31.5360030000
RGRID	530	3.7507() 703	33.03000000000
RGRID	Sou	<b>3.75</b> 07347303	34.5000000000
RGRID	3 7 7	3.75(11),000	35.501000,000
RGP17	7.04	3.7501370301	37.50000000000
RGRID	3 72	3.75 C 0 2.2	39.00000000000
RGRID	2 O Z	3.75.5(1)(3	46.5883800000
RGRID	Z ~ /*	3.75,0 0 071	42.0330003337
RGRID	<b>メレご</b>	3.75,000000	43.5000000000
RGRID	315	<b>3.</b> 7500_u,00u	45.0000000000
RGRID	2 h 3	3.7559231377	46.50000001001
RGRID	3 19	3.7509 70 103	48.00030000000
RGRID	340	3.75.00000000	49.53.310
RGRID	317	3.75(1,5134)	51.18000000000
RGPID	311	3.75(0)00000	52.50(010333)
RGRID	712	7.7E(July 039)	34.00000099800
RGRID	313	3.750000.000	5%.5000000000
RGRID	314	3.7509,00.000	57.0006015000
RGRID	315	3.750000000	58.50000000000
RGRID	716	7.75(j · j · h^j	5:000000000000
RGRID	317	3.750 1000 00J	61.90000000000
RGRID	31°	3.75(70) 509	63.000000000000
RGRID	319	3.75/000/000	64.50000000000
RGRID	₹2:	3.750000 300	66.00000000000
RGRID	3 21	3•75 1939 aug	67.50000003000
RGRID	3 22	3.75(000)000	69.0000000000
RGRIT	323	3.751133 339	7/-50000000000
RGRID	326	3.75101003330	72.00000000000
RGRID	₹ <u>2</u> Γ	3.755 0333 133	73.53006603996
RGRID	325	3.75.000.000	75.00000000001
RGRIO	327	<b>3.</b> 750@agaaca	76.5000000000
RGRID	3 28	3.75.303.3.3	78.6300630000
RGRID	720	3.75.0000300	79.56000000000
RGRID	₹3£	3.750000,10	81.63600000000
RGRID	331	3.75000JU 100	\$2.5090000000
RGRID	<b>332</b>	<b>3.75</b> 0333693 <b>3</b>	84.0900000000
RGRIT	333	3.75(00)(300	85.5000000000
RGRID	334	3.750000.130	87.00000000000
RGRID	335	3.750000 JOD	88.50.06.000000
RGRID	3 3F	<b>3.75</b> 3 0005 930	90.000000000000
RGRID	3 37	3.7575 000 000	0.00000000000
RGRID	3 38	3.7575 TOF 14	1.500000000
RGRID	3 39	<b>3.</b> 7575.00.930	3.3663666999
RGRID	340	3.7575 000 100	4.5000000000
RGRID	341	<b>3.</b> 7575@J0000	6.0000010000
RGRID	342	3.757530.200	7.501000000

			9.0000000000
RGRIT	343	3.7575.3.333	13.5000860066
RGPIO	₹16%	3.7575 000 000	12.000000000000
RGRIJ	345	3.7575.1.170	13.5300000000
RGRID	<b>345</b>	3.757503.313 3.757500 003	15.00.30.001(1
RERIT	マレフ		16.5463674475
RGRIT	REA	3.757516 103	18.00.300.0000
RGRI )	340	3.7575 (0) 193 3.7575 (1) (1)	19.50.00000000
RERES	370		21.0000003005
RGRID	351	3,7575,41710	22.500000000000
RGR1D	772	3.7575 (3.339 3.7575 (3.110	24.64.000017000
RGRID	31.4	3.757379.737	25.535000001L
PGRID	754		27.636866600000
RGRID	रुसद	3.75/5600033	28.50000000000
RGRID	355	3.757365-339	30.00000000000
RGRIN	357	3.7575.3039	31.50000000000
RGRID	रह व	3.7575.3: 110 3.757532 330	33.505000000000
RGRIO	759	3,757532 336 3,7575030333	34.50000000000
PGRID	3F.1		36.5000000000000
RGRID	7 5.1	3.75750303999 3.757571	37.58465 10463
RGRID	76.2	3.757571 JU 3.75777110010	39,00000000000
RGRID	753	3.7575.177.3	41.5000000000
RGRID	366	3.7575 19.313	42.0000000000
RGRID	365	3.7575.91 101	43.5030000000
RGRID	7 5E	3.7576781399	45.0000000000000
RGRID	367	3.75/ 534. 334	46.530300000000
RGRID	76A	3.7575 21:100	48.100000000000
RGRID	369	3.757511 130	49.5668889318
RGRID	ሚምስ 	3.7575001130	51.00000000000
RGRID	371	3.757530.130	52.50.00,000.0
RGRIT	372	3.757512 319	54.1300650666
RGRID	373	3.757503 313	5F.F01965J376
RGRID	376	3.7575604930	57.0000000000
RGRID	375	3.757540.113	58.56603660366
RGRID	376	3.7575040334	60.600000000000
RGRID	377	3.7575.00.134	51.5368663003
RGRID	77A	3.7575333333	53.00000003105
RGRID	379	3.7575:0:110	64.50000000000
RGPIN	390	3.7573,01339	56.0000000000
RGRID	381	3.7575101313	67.50000000000
RGRID	382	3.757540.303	59.600000000000
RGRID	383	3.7575.3 993	70.5000000000
RGRID	384	3.7575 10. 211	72.00000000000
RGRID	385	3.757537 779	73.53605664450
RGRID	38F	3.7575000010	78.00000000000
RGRID	387	3.7575521 390	76.5000000000
RGRID	3 8 8 7 8 0	3.7575:3:330	78.00000000000
RGRID	7,8Q	3.757 500 000	79.5001000000
RGRIT	39 ·	3.7573001000	81.000000000000
RGRID	391	3.7575000330	82.50000000000
RGRID	392	3477 .00 2.10	

RGRID	₹93	•	3.7575300033		84.000000000000
RGRID	391		3.7575.0.100		85.50000000000
RGRID	395		3.7575906 393		87.60000600010
RGRID	705		3.7579 14 195		88.50.3000000
RGRID	397		3.7575 13.303		91.5300003360
TPIL	ນ້ວ	277	278	29	LIF
TRIA	44.0	27 1	29	36	AIR
TRIA	411	273	2 7 7	31	AIR
TRIA	412	273	278	33	AIR
TRIA	413	273	3 '	71	AIR
TRIA	415	28 ]	279	31	AIR
TRIA	41 5	281	23 :	31	AIR
TRIA	51K	281	₹1	32	VIC
TRIA	417	282	231	32	AIR
TRIA	<b>-1</b> 5	283	232	32	AIR
TRIA	110	283	32	33	AIR
TPIA	4 2 5	25 +	283	33	AIF
TRIA	421	285	234	33	AIR
TRIA	422	283	33	34	AIR
TRIA	423	285 287	235 235	34	AIR
TRIA Tria	423 423	287	200 34	34 35	
TRIA	425	283	237	3 <del>4</del>	
TRIA	427	563	238	35	
TRIA	428	289	35	3E	
TRIA	429	29 -	239	36	
TRIA	433	291	296	35	
TRIA	431	291	36	37	
TRIA	432	292	291	37	
TRIA	473	293	29 <i>2</i>	37	
TRIA	434	293	37	38	
TRIA	435	23+	293	38	
TRIA	+36	294	38	39	
TRIA	437	295	294	39	
TRIA	438	295	295	रव	
TRIA	439	295	33	46	
TRIA	448	297	296	47	
TRIA	141	293	297	40	
TRIA	442	293	49 200	41	
TRIA	443	563	298	41	
TRIA Tria	ዓፋል ዓፋማ	303 373	299 . 1	41 42	
TRIA	446	36.1	3าน	42	
TRIA	447	302	3)1	42	
TRIA	448	302	42	43	
TRIA	449	313	302	43	
TRIA	450	393	43	44	
TRIA	451	304	303	44	
TRIA	452	365	30+	44	
TRIA	453	305	44	45	

TRIL	454	305	315	45	
TRIA	5 " =	307	315	45	
TRIA	156	307	45	45	
TRIA	157	3r3	3 17	4 č	
	, <del>7</del> 8	313		46	
TRIA			308		
TRIA	WE 0	7 }	_ +8	47	
TRTL	16.5	311	3:3	47	
TRIL	454	₹13	4.7	48	
TPIA	. 5.2	711	31	+6	
TRIA	46.3	312	311	43	
TRIA	.51	312	٠. ٤	47	
TPIA	400	313	312	47	
TRIA	466	31'4	313	49	
TRIA	46-	314	43	50	
TRIA	468	317	31	5 n	
TRIA	459	315	315	<b>5</b> 0	
	437		517		
TRIA		315		51	
TRIA	471	317	316	51	
TRIA	472	313	317	51	
TPIA	477	313	51	52	
TRIA	376	313	318	52	
TRIA	ኔን C	313	52	53	
TRIA	476	327	319	53	
TRIA	477	321	320	53	
TRIA	478	321	53	54	
TRIA	473	32.2	321	54	
TRIA	490	323	322	54	
TRIA	481	323	56	55	
TRIA	1A 2	32+	323	55	
TRIA	483	325	32.	<b>5</b> 5	
TRIA		32.7		55	
	484		53		
TRIA	<u>ងុខ្ញុំត</u>	325	323	<b>5</b> 6	
TRIA	488	327	325	58	AIR
TRIA	497	327	<u>56</u>	57	AIR
TRIA	488	323	327	57	AIR
TRIA	7 . 4	323	728	57	AIR
TRIA	490	323	57	58	AIR
TRIA	491	331	3 <i>2</i> 9	58	AIR '
TRIA	1.92	331	333	58	AIR
TRIA	493	331	53	59	AĪR
TRIA	494	332	331	59	AIR
TRIA	495	333	332	59	AIR
TRIA	+06	333 333	59	60	AIR
TRIA	497	334	333	63	AIR
TPIA	498 200	33°	336	6.1	AIP
TRIA	¥99	335	50	61	AIR
TRIA	500	335	3 3 5	51	AIR
TRIA	501	333	337	276	AIR
TRIA	££ 5	373	276	277	ATR
TRIA	=13	339	338	27 <b>7</b>	4 I R

TRIA 501 333 277 278 AIR TRIA 506 340 339 278 AIR TRIA 506 340 359 278 AIR TRIA 506 340 359 279 AIR TRIA 507 360 377 279 AIR TRIA 507 360 377 279 AIR TRIA 508 340 357 279 AIR TRIA 508 340 347 279 280 AIR TRIA 509 340 340 281 AIR TRIA 510 341 342 200 281 AIR TRIA 511 344 343 282 AIR TRIA 514 344 343 282 AIR TRIA 514 344 345 282 233 ATR TRIA 514 344 345 282 233 ATR TRIA 517 340 344 282 233 ATR TRIA 517 340 344 282 233 AIR TRIA 517 340 347 280 AIR TRIA 517 340 347 280 AIR TRIA 517 340 347 286 AIR TRIA 520 347 286 AIR TRIA 521 370 347 286 AIR TRIA 522 373 340 287 283 AIR TRIA 523 340 287 283 AIR TRIA 525 350 287 AIR TRIA 527 350 347 280 AIR TRIA 528 350 287 283 AIR TRIA 528 350 240 280 AIR TRIA 528 350 250 291 AIR TRIA 530 352 290 291 AIR TRIA 531 353 352 291 AIR TRIA 532 354 354 292 293 AIR TRIA 533 354 359 292 AIR TRIA 535 355 294 AIR TRIA 537 350 353 294 AIR TRIA 537 350 353 294 AIR TRIA 538 354 359 295 AIR TRIA 537 350 353 294 AIR TRIA 538 357 356 AIR TRIA 540 357 350 393 294 AIR TRIA 541 358 357 296 AIR TRIA 540 357 350 350 299 AIR TRIA 540 357 350 350 299 AIR TRIA 540 357 350 350 299 AIR TRIA 540 350 350 350 299 AIR TRIA 540 350 350 350 299 AIR TRIA 540 350 350 299 AIR TRIA 540 350 360 360 360 AIR TRIA 540 350 350 350 299 AIR TRIA 540 350 360 360 360 AIR TRIA 540 350 350 360 360 AIR TRIA 540 350 360 360 AIR TRIA 540 350 360 360 360 AIR TRIA 540 350 360 360 360 AIR TRIA 540 360 360 360 360 AIR TRIA 540 360 360 360 AIR TRIA 540 3						
TRIA 506 344 279 AIR TRIA 507 361 377 279 AIR TRIA 507 361 279 280 AIR TRIA 508 361 279 280 AIR TRIA 514 542 200 281 AIR TRIA 514 343 362 281 AIR TRIA 517 344 343 282 AIR TRIA 514 544 252 233 ATR TRIA 514 544 252 233 ATR TRIA 517 344 344 252 233 ATR TRIA 517 344 345 283 284 AIR TRIA 517 345 347 280 AIR TRIA 518 347 348 285 AIR TRIA 520 347 348 285 AIR TRIA 520 347 348 285 AIR TRIA 521 343 347 286 AIR TRIA 521 343 347 286 AIR TRIA 522 343 349 283 287 AIR TRIA 523 349 343 287 AIR TRIA 525 350 349 287 283 AIR TRIA 527 351 352 297 AIR TRIA 528 351 352 291 AIR TRIA 528 351 353 292 AIR TRIA 531 353 352 291 AIR TRIA 532 354 355 292 AIR TRIA 535 355 292 AIR TRIA 535 357 295 AIR TRIA 536 357 356 295 AIR TRIA 537 358 357 295 AIR TRIA 538 357 295 AIR TRIA 539 357 356 295 AIR TRIA 539 357 356 292 AIR TRIA 539 357 356 295 AIR TRIA 539 357 356 295 AIR TRIA 540 351 353 292 AIR TRIA 540 351 350 299 AIR TRIA 540 361 361 AIR TRIA 540 362 361 301 AIR TRIA 550 362 361 301 AIR	TFIA	591	333	2**	278	AIR
TRIA 506 344 279 AIR TRIA 507 361 377 279 AIR TRIA 507 361 279 280 AIR TRIA 508 361 279 280 AIR TRIA 514 542 200 281 AIR TRIA 514 343 362 281 AIR TRIA 517 344 343 282 AIR TRIA 514 544 252 233 ATR TRIA 514 544 252 233 ATR TRIA 517 344 344 252 233 ATR TRIA 517 344 345 283 284 AIR TRIA 517 345 347 280 AIR TRIA 518 347 348 285 AIR TRIA 520 347 348 285 AIR TRIA 520 347 348 285 AIR TRIA 521 343 347 286 AIR TRIA 521 343 347 286 AIR TRIA 522 343 349 283 287 AIR TRIA 523 349 343 287 AIR TRIA 525 350 349 287 283 AIR TRIA 527 351 352 297 AIR TRIA 528 351 352 291 AIR TRIA 528 351 353 292 AIR TRIA 531 353 352 291 AIR TRIA 532 354 355 292 AIR TRIA 535 355 292 AIR TRIA 535 357 295 AIR TRIA 536 357 356 295 AIR TRIA 537 358 357 295 AIR TRIA 538 357 295 AIR TRIA 539 357 356 295 AIR TRIA 539 357 356 292 AIR TRIA 539 357 356 295 AIR TRIA 539 357 356 295 AIR TRIA 540 351 353 292 AIR TRIA 540 351 350 299 AIR TRIA 540 361 361 AIR TRIA 540 362 361 301 AIR TRIA 550 362 361 301 AIR	TRIA	៩ភូឌ	341	339	278	ATR
TRIA						
TRIA						
TRIA 519 362 791 281 AIR TRIA 519 344 252 231 AIR TRIA 519 344 252 233 ATR TRIA 517 345 347 283 AIR TRIA 517 345 347 285 AIR TRIA 517 345 347 286 AIR TRIA 517 345 347 286 AIR TRIA 517 345 244 285 AIR TRIA 517 345 244 285 AIR TRIA 517 345 247 286 AIR TRIA 517 345 347 286 AIR TRIA 520 347 286 AIR TRIA 520 347 286 AIR TRIA 520 347 286 AIR TRIA 522 343 285 287 ATR TRIA 523 349 286 AIR TRIA 523 349 286 AIR TRIA 523 349 287 AIR TRIA 528 350 289 AIR TRIA 527 351 352 291 291 AIR TRIA 531 352 351 291 AIR TRIA 531 352 351 291 AIR TRIA 532 353 352 291 AIR TRIA 531 352 353 352 291 AIR TRIA 531 353 352 291 AIR TRIA 532 353 354 292 AIR TRIA 535 355 292 AIR TRIA 535 355 293 AIR TRIA 536 357 295 AIR TRIA 537 358 357 295 AIR TRIA 541 358 357 295 296 AIR TRIA 542 359 357 295 AIR TRIA 542 359 357 295 AIR TRIA 542 359 359 297 AIR TRIA 543 359 297 AIR TRIA 544 359 357 295 296 AIR TRIA 544 359 297 297 AIR TRIA 544 359 297 297 AIR TRIA 547 351 358 357 299 AIR TRIA 548 359 359 299 AIR TRIA 548 359 297 297 AIR TRIA 548 359 359 299 AIR TRIA 548 359 299 299 AIR TRIA 549 359 299 299 AIR TRIA 549 359 299 AIR TRI						
TRIA					291	
TRIA	TRIA	7 9	367	7 +1	23 (	2 IP
TRIA	TOTA	54.6	342	233	281	ATE
TRIA						
TRIA						
TRIA						
TRIA	TRIA				282	AIR
TRIA	TRIA	714	364	25 <i>2</i>	233	ATR
TRIA 717 345 283 284 AIR TRIA 717 345 34F 286 AIR TRIA 718 345 284 285 AIR TRIA 517 347 356 284 285 AIR TRIA 527 347 286 AIR TRIA 721 763 347 286 AIR TRIA 722 373 285 287 AIR TRIA 523 343 283 287 AIR TRIA 523 343 283 287 AIR TRIA 524 369 287 283 AIR TRIA 525 360 349 287 283 AIR TRIA 526 367 351 289 AIR TRIA 527 361 351 239 290 AIR TRIA 528 361 239 290 AIR TRIA 531 352 351 291 AIR TRIA 531 353 352 291 AIR TRIA 532 363 364 292 AIR TRIA 533 364 292 293 AIR TRIA 533 364 292 293 AIR TRIA 535 365 357 294 AIR TRIA 537 365 357 296 AIR TRIA 538 367 396 397 AIR TRIA 537 365 367 299 296 AIR TRIA 538 367 399 296 AIR TRIA 539 357 356 299 AIR TRIA 540 359 357 299 296 AIR TRIA 541 359 357 299 296 AIR TRIA 541 359 357 299 296 AIR TRIA 542 369 367 376 299 AIR TRIA 543 369 367 299 296 AIR TRIA 544 369 296 297 AIR TRIA 547 351 359 299 AIR TRIA 548 369 367 299 AIR TRIA 548 369 367 299 AIR TRIA 548 369 369 391 AIR TRIA 548 369 369 299 AIR TRIA 548 369 369 299 AIR TRIA 548 369 360 391 AIR TRIA 548 361 299 305 AIR TRIA 548 361 299 305 AIR TRIA 549 362 361 301 AIR TRIA 550 362 301 AIR		51F '		3		ATR
TRIA 517 345 346 286 AIR TRIA 519 347 346 285 AIR TRIA 519 347 346 285 AIR TRIA 529 347 286 AIR TRIA 529 348 285 AIR TRIA 529 348 285 AIR TRIA 528 349 285 287 AIR TRIA 528 349 287 286 AIR TRIA 528 349 287 286 AIR TRIA 528 369 287 286 AIR TRIA 527 361 351 289 AIR TRIA 529 352 351 291 AIR TRIA 531 352 391 291 AIR TRIA 531 353 352 291 AIR TRIA 531 353 352 291 AIR TRIA 533 354 292 AIR TRIA 535 365 367 292 AIR TRIA 536 367 368 292 AIR TRIA 537 366 367 298 AIR TRIA 538 367 299 296 AIR TRIA 539 357 299 296 AIR TRIA 539 357 299 296 AIR TRIA 541 358 357 299 296 AIR TRIA 541 358 357 299 296 AIR TRIA 541 358 357 299 296 AIR TRIA 543 369 357 299 296 AIR TRIA 544 359 297 298 AIR TRIA 545 369 367 299 296 AIR TRIA 546 369 297 AIR TRIA 547 351 359 299 AIR TRIA 548 369 357 299 296 AIR TRIA 548 369 357 299 296 AIR TRIA 549 369 360 AIR TRIA 548 369 369 299 AIR TRIA 549 369 360 AIR TRIA 548 369 369 299 AIR TRIA 548 369 360 301 AIR TRIA 549 362 361 300 AIR TRIA 549 362 361 300 AIR TRIA 550 362 301 AIR TRIA 550 362 301 AIR TRIA 551 363 362 301 AIR TRIA 551 363 362 301 AIR TRIA 551 363 362 301 AIR TRIA 552 363 361 302 AIR						
TRIA 519 347 356 286 AIR TRIA 520 367 285 286 AIR TRIA 520 367 285 286 AIR TRIA 521 763 347 286 AIR TRIA 522 373 247 286 AIR TRIA 523 343 247 286 AIR TRIA 523 343 245 287 AIR TRIA 528 369 287 283 AIR TRIA 525 350 349 284 AIR TRIA 525 350 349 284 AIR TRIA 525 350 349 280 AIR TRIA 527 351 354 289 AIR TRIA 528 351 290 AIR TRIA 531 352 351 291 AIR TRIA 531 353 352 291 AIR TRIA 533 354 292 AIR TRIA 533 354 292 AIR TRIA 533 354 292 AIR TRIA 535 355 291 AIR TRIA 535 357 356 292 AIR TRIA 537 358 357 291 AIR TRIA 538 357 356 291 AIR TRIA 539 357 356 291 AIR TRIA 539 357 356 291 AIR TRIA 539 357 356 291 AIR TRIA 540 359 357 356 299 AIR TRIA 540 359 357 295 AIR TRIA 540 359 357 295 AIR TRIA 540 359 357 299 296 AIR TRIA 541 358 357 295 AIR TRIA 542 359 296 AIR TRIA 543 359 357 296 AIR TRIA 544 359 357 299 296 AIR TRIA 543 359 357 299 296 AIR TRIA 544 359 357 299 296 AIR TRIA 547 351 350 299 AIR TRIA 548 369 297 299 AIR TRIA 548 369 297 299 AIR TRIA 548 369 299 AIR TRIA 549 361 360 299 AIR TRIA 549 361 360 AIR TRIA 549 362 301 AIR TRIA 550 362 301 AIR TRIA 550 362 301 AIR TRIA 551 363 362 301 AIR TRIA 552 363 361 302 AIR						
TRIA 519 347 336 285 AIR TRIA 520 367 286 AIR TRIA 521 363 347 286 AIR TRIA 522 373 285 267 ATR TRIA 523 343 285 267 ATR TRIA 523 343 285 267 ATR TRIA 523 343 285 287 AIR TRIA 528 369 287 283 AIR TRIA 526 360 349 280 AIR TRIA 526 360 349 280 AIR TRIA 527 351 351 283 289 AIR TRIA 528 361 239 290 AIR TRIA 528 361 239 290 AIR TRIA 528 361 239 291 AIR TRIA 531 353 352 291 AIR TRIA 531 353 352 291 AIR TRIA 533 354 353 292 AIR TRIA 535 355 354 292 AIR TRIA 535 355 354 293 AIR TRIA 536 357 356 293 AIR TRIA 537 358 357 294 AIR TRIA 538 357 356 295 AIR TRIA 539 357 356 295 AIR TRIA 541 359 357 296 AIR TRIA 541 359 357 299 296 AIR TRIA 543 369 399 AIR TRIA 544 359 297 299 AIR TRIA 546 361 360 AIR TRIA 548 361 299 300 AIR TRIA 548 361 299 300 AIR TRIA 548 361 299 300 AIR TRIA 548 361 399 300 AIR TRIA 550 362 301 AIR TRIA 550 362 301 AIR TRIA 551 363 362 301 AIR TRIA 551 363 362 301 AIR						
TRIA 520 367 286 AIR TRIA 521 363 347 286 AIR TRIA 523 363 285 267 ATR TRIA 523 363 287 283 AIR TRIA 528 369 287 283 AIR TRIA 528 369 287 283 AIR TRIA 526 360 369 287 283 AIR TRIA 526 360 351 289 AIR TRIA 527 361 351 290 AIR TRIA 520 362 361 291 AIR TRIA 531 353 352 291 AIR TRIA 533 364 292 AIR TRIA 535 365 365 292 AIR TRIA 536 365 365 294 AIR TRIA 537 366 365 294 AIR TRIA 539 367 376 296 AIR TRIA 539 367 376 296 AIR TRIA 540 351 358 297 296 AIR TRIA 540 351 358 297 296 AIR TRIA 540 351 358 297 298 AIR TRIA 540 351 358 297 298 AIR TRIA 540 351 351 297 298 AIR TRIA 541 358 357 296 AIR TRIA 542 369 297 AIR TRIA 544 369 297 298 AIR TRIA 544 369 297 298 AIR TRIA 545 361 361 361 AIR TRIA 548 361 299 306 AIR TRIA 548 361 299 306 AIR TRIA 550 362 301 AIR TRIA 550 362 301 AIR TRIA 550 362 301 AIR						
TRIA	TRIA		34 7	3 →€	2.85	1 IR
TRIA	TRIA	250	367	235	285	AIR
TRIA 528 3/3 285 287 AIR TRIA 528 343 343 287 283 AIR TRIA 528 369 287 283 AIR TRIA 526 360 349 283 AIR TRIA 526 360 349 283 AIR TRIA 527 361 35, 283 AIR TRIA 527 361 35, 283 AIR TRIA 528 361 361 AIR TRIA 531 353 352 291 AIR TRIA 531 353 352 291 AIR TRIA 531 353 352 291 AIR TRIA 533 354 292 AIR TRIA 533 354 292 AIR TRIA 535 355 354 293 AIR TRIA 535 365 357 296 AIR TRIA 537 365 355 294 AIR TRIA 537 365 357 296 AIR TRIA 538 357 356 295 AIR TRIA 540 351 352 297 AIR TRIA 540 351 352 297 AIR TRIA 541 358 357 295 AIR TRIA 544 359 357 295 AIR TRIA 544 359 357 295 AIR TRIA 545 351 359 297 AIR TRIA 546 351 359 297 AIR TRIA 547 351 359 296 AIR TRIA 548 359 357 295 AIR TRIA 548 359 359 297 AIR TRIA 548 359 359 299 AIR TRIA 548 359 359 399 AIR TRIA 548 359 359 399 AIR TRIA 548 351 351 301 AIR TRIA 550 362 351 301 AIR			763	37		
TRIA 528 349 287 283 AIR TRIA 526 360 349 286 AIR TRIA 526 360 349 286 AIR TRIA 526 360 349 286 AIR TRIA 526 361 351 289 AIR TRIA 527 361 351 289 AIR TRIA 529 352 351 291 AIR TRIA 531 353 352 291 AIR TRIA 531 353 352 291 AIR TRIA 532 361 292 AIR TRIA 533 364 392 AIR TRIA 533 364 392 AIR TRIA 535 365 361 AIR TRIA 536 361 361 AIR TRIA 548 361 369 361 AIR TRIA 548 361 369 361 AIR TRIA 548 361 369 361 AIR TRIA 548 361 362 361 AIR TRIA 559 362 362 361 AIR TRIA 559 362 361 AIR TRIA 548 361 362 361 AIR TRIA 559 362 361 AIR TRIA 550 362 361 AIR						
TRIA 524 369 287 283 AIR TRIA 525 350 349 280 AIR TRIA 525 350 283 289 AIR TRIA 527 351 35. 289 AIR TRIA 527 351 35. 289 AIR TRIA 529 352 351 297 AIR TRIA 530 352 291 AIF TRIA 531 353 352 291 AIF TRIA 531 353 352 291 AIR TRIA 533 354 292 AIR TRIA 533 354 393 AIR TRIA 535 355 291 AIR TRIA 536 357 356 292 AIR TRIA 537 355 357 295 AIR TRIA 537 355 357 295 AIR TRIA 539 357 356 295 AIR TRIA 539 357 356 295 AIR TRIA 540 353 359 297 AIR TRIA 541 358 357 295 296 AIR TRIA 542 359 296 AIR TRIA 543 359 357 295 296 AIR TRIA 544 359 359 297 AIR TRIA 545 351 359 299 AIR TRIA 547 351 359 299 AIR TRIA 548 361 359 299 AIR TRIA 548 361 359 399 AIR TRIA 548 361 359 399 AIR TRIA 548 361 359 399 AIR TRIA 548 361 359 390 AIR TRIA 559 362 351 301 AIR TRIA 550 362 351 301 AIR TRIA 550 362 351 301 AIR TRIA 550 362 351 301 AIR						
TRIA 525 350 349 280 AIR TRIA 525 351 357 356 AIR TRIA 527 351 357 295 AIR TRIA 527 351 357 295 AIR TRIA 528 357 357 295 AIR TRIA 528 357 358 292 AIR TRIA 535 357 356 357 295 AIR TRIA 536 357 357 295 AIR TRIA 540 357 295 AIR TRIA 541 358 357 295 AIR TRIA 542 359 359 297 AIR TRIA 543 359 359 297 AIR TRIA 544 359 295 297 AIR TRIA 544 359 295 297 AIR TRIA 544 359 359 299 AIR TRIA 544 359 297 AIR TRIA 548 361 299 300 AIR TRIA 549 362 351 300 AIR TRIA 550 362 301 AIR TRIA 550 360 360 360 360 360 360 360 360 360 36						
TRIA 525 351 233 290 AIR TRIA 527 351 35. 233 AIR TRIA 528 351 233 290 AIR TRIA 529 352 351 291 AIR TRIA 531 353 352 291 AIR TRIA 531 353 352 291 AIR TRIA 532 353 292 AIR TRIA 533 354 292 AIR TRIA 535 355 292 AIR TRIA 535 355 354 293 AIR TRIA 537 355 353 294 AIR TRIA 537 355 353 294 AIR TRIA 537 355 357 295 AIR TRIA 538 357 295 AIR TRIA 540 357 299 296 AIR TRIA 541 358 357 295 AIR TRIA 541 358 357 295 AIR TRIA 542 353 359 297 AIR TRIA 543 359 359 297 AIR TRIA 544 359 295 297 AIR TRIA 545 351 359 299 AIR TRIA 546 351 299 299 AIR TRIA 547 351 359 299 AIR TRIA 548 361 299 300 AIR TRIA 548 361 299 300 AIR TRIA 548 361 299 300 AIR TRIA 549 362 351 300 AIR TRIA 550 362 301 AIR						
TRIA 528 351 239 290 AIR TRIA 528 351 239 290 AIR TRIA 529 352 351 291 AIR TRIA 531 353 352 291 AIR TRIA 531 353 352 291 AIR TRIA 533 354 292 AIR TRIA 533 354 292 AIR TRIA 533 354 292 293 AIR TRIA 535 355 354 293 AIR TRIA 535 355 354 293 AIR TRIA 535 355 357 294 AIR TRIA 537 355 355 294 AIR TRIA 537 355 355 294 AIR TRIA 539 357 356 295 AIR TRIA 540 357 358 357 295 AIR TRIA 541 358 357 295 AIR TRIA 541 358 357 295 AIR TRIA 542 358 296 297 AIR TRIA 543 359 359 296 AIR TRIA 544 359 359 296 AIR TRIA 545 351 359 297 AIR TRIA 546 351 296 297 AIR TRIA 547 351 359 297 AIR TRIA 548 359 359 299 AIR TRIA 548 351 299 306 AIR TRIA 548 351 299 306 AIR TRIA 548 351 299 306 AIR TRIA 548 351 391 302 AIR TRIA 550 362 351 300 AIR TRIA 550 362 351 300 AIR TRIA 551 353 362 301 AIR	TRIA	25 E	3 ਵਾਲ	349	283	AIR
TRIA 528 351 239 296 AIR TRIA 528 351 290 291 AIR TRIA 529 352 290 291 AIR TRIA 531 353 352 291 AIR TRIA 531 353 352 291 AIR TRIA 532 353 292 AIR TRIA 533 354 292 AIR TRIA 533 354 292 293 AIR TRIA 535 355 354 293 AIR TRIA 535 355 354 293 AIR TRIA 535 355 357 294 AIR TRIA 537 355 355 294 AIR TRIA 537 355 355 294 AIR TRIA 539 357 356 295 AIR TRIA 540 357 358 357 295 AIR TRIA 541 358 357 295 AIR TRIA 541 358 357 295 AIR TRIA 541 358 357 295 AIR TRIA 542 358 296 297 AIR TRIA 543 359 359 296 AIR TRIA 544 359 296 297 AIR TRIA 544 359 359 296 AIR TRIA 545 351 359 297 AIR TRIA 546 351 298 299 AIR TRIA 547 351 350 298 299 AIR TRIA 548 361 299 306 AIR TRIA 548 361 299 306 AIR TRIA 548 361 299 306 AIR TRIA 549 362 351 308 AIR TRIA 550 362 301 AIR TRIA 550 362 301 AIR	TPIA	525	357	233	283	AIR
TPIA 528 351 239 296 AIR TRIA 529 352 351 297 AIR TRIA 531 353 352 291 AIR TRIA 531 353 352 291 AIR TRIA 532 353 292 AIR TRIA 533 354 353 292 AIR TRIA 534 354 292 293 AIR TRIA 535 355 354 293 AIR TRIA 535 355 354 293 AIR TRIA 535 355 354 293 AIR TRIA 537 355 355 294 AIR TRIA 537 355 355 294 AIR TRIA 539 357 356 295 AIR TRIA 540 357 358 357 295 AIR TRIA 541 358 357 295 AIR TRIA 541 358 357 295 AIR TRIA 542 358 296 297 AIR TRIA 543 359 359 296 AIR TRIA 544 359 359 296 AIR TRIA 545 351 359 297 AIR TRIA 546 351 296 297 AIR TRIA 547 351 350 298 299 AIR TRIA 548 351 299 306 AIR TRIA 548 351 391 300 AIR TRIA 550 362 351 300 AIR TRIA 550 362 351 300 AIR TRIA 551 353 362 301 AIR TRIA 552 353 351 302 AIR	TRIA	727		35.	234	
TRIA 529 352 351 297 AIR TRIA 531 352 290 291 AIR TRIA 531 353 352 291 AIR TRIA 531 353 352 291 AIR TRIA 532 353 292 AIR TRIA 533 354 292 AIR TRIA 535 354 292 293 AIR TRIA 535 355 354 293 AIR TRIA 535 355 354 293 AIR TRIA 535 355 294 AIR TRIA 537 365 355 294 AIR TRIA 537 365 355 294 AIR TRIA 538 357 356 295 AIR TRIA 540 357 299 296 AIR TRIA 541 358 357 295 AIR TRIA 541 358 357 295 AIR TRIA 542 359 296 AIR TRIA 543 359 359 297 AIR TRIA 544 359 296 AIR TRIA 545 361 359 299 AIR TRIA 546 361 369 299 AIR TRIA 547 351 350 299 AIR TRIA 548 361 299 305 AIR TRIA 548 361 299 305 AIR TRIA 549 362 351 300 AIR TRIA 559 362 351 300 AIR						
TRIA 531 352 291 AIR TRIA 531 353 352 291 AIR TRIA 632 353 291 292 AIR TRIA 633 354 353 292 AIR TRIA 634 354 292 293 AIR TRIA 635 355 354 293 AIR TRIA 635 355 354 293 AIR TRIA 635 355 294 AIR TRIA 637 365 355 294 AIR TRIA 637 365 355 294 AIR TRIA 638 357 356 295 AIR TRIA 639 357 356 295 AIR TRIA 640 357 295 296 AIR TRIA 641 358 357 296 AIR TRIA 642 358 296 297 AIR TRIA 644 359 296 297 AIR TRIA 644 359 296 AIR TRIA 644 359 296 AIR TRIA 645 361 369 299 AIR TRIA 646 361 299 306 AIR TRIA 647 351 350 299 AIR TRIA 648 361 299 306 AIR TRIA 648 361 299 306 AIR TRIA 648 361 299 306 AIR TRIA 659 362 351 300 AIR TRIA 559 362 351 300 AIR						
TRIA 531 353 352 291 AIR TRIA 533 354 353 292 AIR TRIA 535 354 292 293 AIR TRIA 535 354 292 293 AIR TRIA 535 355 294 AIR TRIA 535 355 294 AIR TRIA 537 355 355 294 AIR TRIA 538 357 356 295 AIR TRIA 538 357 295 296 AIR TRIA 540 357 295 296 AIR TRIA 541 358 357 295 296 AIR TRIA 541 358 357 295 297 AIR TRIA 542 358 295 297 AIR TRIA 544 359 359 297 AIR TRIA 545 351 359 297 AIR TRIA 546 351 298 299 AIR TRIA 547 351 350 298 AIR TRIA 548 361 299 AIR TRIA 548 361 299 AIR TRIA 548 361 299 AIR TRIA 549 362 351 300 AIR TRIA 549 362 351 300 AIR TRIA 559 363 363 362 301 AIR TRIA 559 363 363 362 301 AIR TRIA 559 363 363 362 301 AIR TRIA 559 363 363 363 361 AIR TRIA 559 363 363 363 361 AIR TRIA 559 363 363 363 363 363 363 AIR TRIA 559 363 363 363 363 363 AIR TRIA 559 363 363 363 363 363 AIR TRIA 559 363 363 363 363 363 363 AIR TRIA 559 363 363 363 363 363 AIR TRIA 559 363 363 363 363 363 363 AIR TRIA 559 363 363 363 363 363 AIR TRIA 559 363 363 363 363 363 AIR TRIA 559 363 363 363 363 363 363 AIR TRIA 559 363 363 363 363 363 AIR TRIA 559 363 363 363 363 363 AIR TRIA 559 363 363 363 363 AIR TRIA 559 363 363 363 363 363 AIR TRIA 559 363 363 363 363 AIR TRIA 559 363 AIR						
TRIA 532 353 291 AIR TRIA 533 354 353 292 AIR TRIA 535 354 292 293 AIR TRIA 535 355 354 293 AIR TRIA 535 355 354 293 AIR TRIA 535 355 294 AIR TRIA 537 356 353 294 AIR TRIA 538 357 356 295 AIR TRIA 539 357 356 295 AIR TRIA 540 357 295 296 AIR TRIA 541 358 357 295 296 AIR TRIA 541 358 357 295 296 AIR TRIA 542 358 296 297 AIR TRIA 543 359 359 297 AIR TRIA 544 359 296 297 AIR TRIA 545 351 350 298 AIR TRIA 546 351 298 299 AIR TRIA 547 351 350 298 AIR TRIA 548 361 299 306 AIR TRIA 549 362 351 300 AIR TRIA 559 362 351 300 AIR TRIA 559 362 351 300 AIR TRIA 551 353 362 301 AIR TRIA 552 363 361 362 AIR						
TRIA 533 354 353 292 AIR TRIA 534 354 292 293 AIR TRIA 535 355 354 293 AIR TRIA 535 355 354 293 AIR TRIA 535 355 294 AIR TRIA 537 355 355 294 AIR TRIA 538 357 356 295 AIR TRIA 539 357 356 295 AIR TRIA 540 357 295 296 AIR TRIA 541 358 357 295 296 AIR TRIA 541 358 357 295 AIR TRIA 542 358 296 297 AIR TRIA 543 359 359 297 AIR TRIA 544 359 296 297 AIR TRIA 545 351 350 298 AIR TRIA 546 351 298 299 AIR TRIA 547 351 350 299 AIR TRIA 548 361 299 306 AIR TRIA 549 362 351 300 AIR TRIA 559 362 351 300 AIR TRIA 559 362 351 300 AIR TRIA 551 353 362 301 AIR TRIA 552 363 361 362						
TRIA 534 354 292 293 AIR TRIA 535 355 354 293 AIR TRIA 535 355 294 AIR TRIA 537 355 355 294 AIR TRIA 538 355 294 295 AIR TRIA 539 357 356 295 AIR TRIA 546 357 295 296 AIR TRIA 541 358 357 295 296 AIR TRIA 542 358 295 297 AIR TRIA 543 359 359 295 297 AIR TRIA 544 359 359 297 AIR TRIA 545 351 359 295 AIR TRIA 546 351 295 299 AIR TRIA 547 351 350 299 AIR TRIA 548 361 299 300 AIR TRIA 549 362 351 300 AIR TRIA 559 362 351 300 AIR TRIA 559 362 351 300 AIR TRIA 551 353 362 301 AIR TRIA 552 363 361 302 AIR		533		353		
TRIA 535 355 354 293 AIR TRIA 575 355 294 AIR TRIA 537 355 355 294 AIR TRIA 538 355 294 295 AIR TRIA 539 357 356 295 AIR TRIA 540 357 295 296 AIR TRIA 541 358 357 295 296 AIR TRIA 542 358 296 297 AIR TRIA 543 359 359 297 AIR TRIA 544 359 359 297 AIR TRIA 545 351 350 298 AIR TRIA 546 351 298 299 AIR TRIA 547 351 350 299 AIR TRIA 548 361 299 306 AIR TRIA 549 362 351 300 AIR TRIA 550 362 351 300 AIR TRIA 551 353 362 301 AIR TRIA 552 363 361 362 AIR						
TRIA 575 355 294 AIR TRIA 537 355 353 294 AIR TRIA 538 355 294 295 AIR TRIA 539 357 356 295 AIR TRIA 540 357 295 296 AIR TRIA 541 358 357 296 AIR TRIA 542 359 296 297 AIR TRIA 543 359 359 297 AIR TRIA 544 359 296 297 AIR TRIA 544 359 296 297 AIR TRIA 545 351 350 299 AIR TRIA 546 351 299 299 AIR TRIA 547 351 350 299 AIR TRIA 548 361 299 300 AIR TRIA 549 362 351 300 AIR TRIA 559 362 351 300 AIR TRIA 559 362 351 301 AIR TRIA 551 353 362 301 AIR TRIA 552 363 391 302 AIR						
TRIA 537 355 353 294 AIR TRIA 538 355 294 295 AIR TRIA 539 357 356 295 AIR TRIA 540 357 295 296 AIR TRIA 541 358 357 295 296 AIR TRIA 541 358 357 295 AIR TRIA 542 359 296 297 AIR TRIA 543 359 359 297 AIR TRIA 544 359 359 297 AIR TRIA 545 361 360 298 AIR TRIA 546 361 298 299 AIR TRIA 547 351 350 299 AIR TRIA 549 362 351 308 AIR TRIA 559 362 351 308 AIR TRIA 559 362 351 308 AIR TRIA 551 353 362 301 AIR TRIA 552 363 391 302 AIR						
TRIA 538 355 294 295 AIR TRIA 539 357 356 295 AIR TRIA 540 357 295 296 AIR TRIA 541 358 357 295 296 TRIA 541 358 357 295 AIR TRIA 542 359 296 297 AIR TRIA 543 359 359 297 AIR TRIA 544 359 359 297 AIR TRIA 545 361 350 298 AIR TRIA 546 361 298 299 AIR TRIA 547 351 350 299 AIR TRIA 549 362 351 308 AIR TRIA 549 362 351 308 AIR TRIA 559 362 351 308 AIR TRIA 559 362 351 308 AIR TRIA 552 363 391 302 AIR						
TRIA 539 357 356 295 AIR TRIA 540 357 295 296 AIR TRIA 541 358 357 295 AIR TRIA 541 358 357 296 AIR TRIA 542 359 296 297 AIR TRIA 543 359 359 297 AIR TRIA 544 359 297 298 AIR TRIA 546 351 350 298 AIR TRIA 546 351 298 299 AIR TRIA 547 351 350 299 AIR TRIA 549 361 299 300 AIR TRIA 549 362 351 300 AIR TRIA 559 362 351 300 AIR TRIA 551 353 362 301 AIR TRIA 552 363 391 302 AIR						
TRIA 54° 357 295 296 AIR TRIA 541 358 357 296 AIR TRIA 542 358 296 297 AIR TRIA 543 359 359 297 AIR TRIA 544 359 297 298 AIR TRIA 546 361 369 298 AIR TRIA 546 361 298 299 AIR TRIA 547 351 350 299 AIR TRIA 548 361 299 300 AIR TRIA 549 362 351 300 AIR TRIA 559 362 351 300 AIR TRIA 559 362 351 300 AIR TRIA 551 353 362 301 AIR TRIA 552 363 391 302 AIR						
TRIA 341 358 357 295 AIR TRIA 542 358 296 297 AIR TRIA 543 359 359 297 AIR TRIA 544 359 297 298 AIR TRIA 544 359 297 298 AIR TRIA 546 361 350 298 299 AIR TRIA 546 361 351 299 AIR TRIA 548 361 299 300 AIR TRIA 549 362 351 300 AIR TRIA 559 362 351 300 AIR TRIA 551 353 362 301 AIR TRIA 552 363 391 302 AIR		539				AIR
TRIA 542 359 296 297 AIR TRIA 543 359 359 297 AIR TRIA 544 359 297 299 AIR TRIA 545 361 350 298 AIR TRIA 546 361 298 299 AIR TRIA 547 361 351 299 AIF TRIA 548 361 299 300 AIR TRIA 549 362 351 300 AIR TRIA 559 362 351 300 AIR TRIA 551 363 362 301 AIR TRIA 552 363 391 302 AIR	TRIA	54 P	357	295	296	AIR
TRIA 542 359 296 297 AIR TRIA 543 359 359 297 AIR TRIA 544 359 297 299 AIR TRIA 545 361 350 298 AIR TRIA 546 361 298 299 AIR TRIA 547 361 351 299 AIF TRIA 548 361 299 300 AIR TRIA 549 362 351 300 AIR TRIA 559 362 351 300 AIR TRIA 551 363 362 301 AIR TRIA 552 363 391 302 AIR	TRIA	541	358	357	295	AIR
TRIA 543 359 359 297 ATR TRIA 546 351 351 298 AIR TRIA 546 351 351 298 299 AIR TRIA 547 351 351 299 AIR TRIA 548 361 299 300 AIR TRIA 548 361 299 300 AIR TRIA 549 362 351 300 AIR TRIA 550 362 351 300 AIR TRIA 551 353 362 301 AIR TRIA 552 363 391 302 AIR		542				
TRIA 544 359 297 298 AIR TRIA 545 360 350 298 AIR TRIA 546 351 298 299 AIR TRIA 547 351 350 299 AIR TRIA 548 361 299 300 AIR TRIA 549 362 351 300 AIR TRIA 550 362 351 300 AIR TRIA 551 363 362 301 AIR TRIA 552 363 391 302 AIR						
TRIA 546 361 359 299 AIR TRIA 546 351 298 299 AIR TRIA 547 351 350 299 AIR TRIA 548 361 299 300 AIR TRIA 549 362 351 300 AIR TRIA 550 362 351 300 AIR TRIA 551 363 362 301 AIR TRIA 552 363 391 302 AIR						
TRIA 546 352 298 299 AIR TRIA 547 351 353 299 AIR TRIA 548 361 299 300 AIR TRIA 549 362 351 300 AIR TRIA 550 362 351 300 AIR TRIA 551 363 362 301 AIR TRIA 552 363 391 302 AIR						
TRIA 547 351 351 299 AIF TRIA 548 361 299 300 AIR TRIA 549 362 351 300 AIR TRIA 550 362 356 361 AIR TRIA 551 363 362 301 AIR TRIA 552 363 391 302 AIR						
TRIA 548 361 299 300 AIR TRIA 549 362 351 300 AIR TRIA 550 362 336 361 AIR TRIA 551 363 362 301 AIR TRIA 552 363 391 302 AIR						
TRIA 54.9 362 351 308 AIR TRIA 550 362 316 361 AIR TRIA 551 363 362 301 AIR TRIA 552 363 391 302 AIR	TRIA			350		
TRIA 350 362 336 361 AIR TRIA 551 363 362 301 AIR TRIA 552 363 391 302 AIR		548			300	
TRIA 551 363 362 301 AIR TRIA 552 363 391 302 AIR	TRIA		362		300	AIR
TRIA 552 363 391 302 AIR	TRIA		362	326	361	AIR
TRIA 552 363 361 302 AIR	TRIA	551	353	362	301	AIR
	TRIA	552	363	391	302	AIR
		553				

TRIA	356	364	312	303	AIR
TRIA	355	363	364	303	AIR
TRIA	556	365	333	304	AIR
TRIA	557	365	355	304	AIR
TRIA	F = 8	365	304	365	AIR
TRIA	7 <u>5</u> a	367	356	3 05	AIR
TPIA	ร์ธิ อ	357	315	306	AIR
TRIA	56 <b>1</b>	363	357	336	AIR
TRIA	362	363	336	397	AIR
TRIA	553	369	353	307	AIR
TRIA	564	353	307	308	AIR
TRIA	565	373	359	386	AIR
TRIA	366	37.1	319	369	AIR
TRIA	567	371	375	309	AIR
TPIA	358	371	313	310	AIR
TRIA	×59	372	371	310	AIR
TRIA	27 J	372	313	311	AIR
TRIA	571	373	372	311	AIR
TRIA	572	37 3	311	312	AIR
TRIA	37°	374	373	312	AIR
TRIA	574	374	31.2	313	AIR
	775	3/ + 373	374	313	AIR
TRIA		373	313	314	AIR
TRIA	576 577	375	375	314	AIR
TRIA	5 <b>7</b> 8	375	315	315	AIR
TRIA	579 579	377	375	31.5	AIR
TRIA	280	377	315		AIR
TRIA	F9.1		377	315 316	AIR
TRIA		373			
TRIA	78.2 78.3	373	316 378	317 247	AIR Alr
TRIA		373 373		317	AIR
TRIA	584. 785	373	317	318	
TRIA	79 K	39.1 39.1	379 315	318 319	AIR AIR
TRIA	<b>≈0.4</b>		30		PIP
TPIA TPIA	# B B	391 391	313	319 320	AIR
	76.5 78.9	392	331	320	AIR
TRIA TRIA	779 7 <b>0</b> 9	382	323	321	AIR
TRIA	701	302 383	332	321	AIR
	F 9 2	383	321	322	AIR
TRIA	593	38'i	321 393	322	AIR
TRIA	594	•			
TRIA	294 505	384	322	323	AIR AIR
TRIA	796	387 383	33+ 323	323 32+	AIR
TRIA	<b>797</b>		31.	321	AIE
TRIA	798	385 385	37. 32h	3 215	
TRIA			3 4 6 3 4 6		AIR AIR
TRIA	2 0 G	201		324	
TOTA	300 301	38 * 393	325 337	325 325	AIR AIR
TRIA	30 2	377 388	325	327	AIR
TRIA			388	327	AIR
TRIA	513	383	300	361	HTK

TRIS	SOL	383	327	329	AIR
TRIA	<b>ភ្</b> ាត	39)	389	328	AIR
TRIA	5, 5, 6	791	328	329	AIR
TRIA	517	301	39.	329	AIR
TPIN	5,10	391	323	330	AIR
TRIA	£ 10	333	391	33	AIR
TRIA	= 10	392	33.	331	AIR
TRIA	511	393	332	331	AIR
TRIA	12	393	771	332	AIR
TRIA	513	39∢	333	332	AIR
TRIA	51/	75	332	333	AIR
TRIA	515	393	394	333	AIR
TRII	515	395	333	33+	AIR
TRIA	517	325	375	334	AIR
TRIA	518	395	334	3.35	AlR
TRIA	51.9	397	336	3 3£	AIR
TRIA	630	397	335	₹ <b>3</b> €	AIR
TRIA	521	215	21%	3 <b>37</b>	AIR
TRIA	522	215	337	333	AIR
TRIA	523	21 7	215	3 <b>3</b> 8	AIF
TRIA	526	217	338	2.33	AIR
TRIA	525	213	217	3 3 3	AIR
TRIA .	526	213	339	3144	AIR
TRIA	627	213	218	340	AIR
TRIA	328	513	340	341	AIP
TRIA	523	22!	219	344	AIF
TRIA	530	551	341	342	AIR
TRIA	531	221	220	342	AIR
TRIA	532	221	342	343	AIR
TRIA	533	722	221	343	AIR
TRIA	534	222	343	341	AIR
TRIA	535	223	222	344	AIR
TRIA	575	223	344	345	AIK
TRIA	537	224	223	345	AIR
TRIA	578	224	345	346	AIR
TRIA	539	225	224	346	AIR
TRIA	540	225	346	347	AIR
TRIA	541	223	225	347	AIR
TRIA	542	223	347	348	AIR
TRIA	543	227	226	348	AIR
TRIA	214	227	348	349	AIR
TRIA	545	223	227	349	AIR
TRIA	365	223	349	356	AIR
TRIA	547	223	223	35°	AIR
TRIA TRIA	549	223 231	350 229	351 351	AIR AIR
TRIA	SER	277	371	352	AIR
TRIA	551	231	232	352 352	AIR
TRIA	5 F 2	231	352	353	AIR
TRIA	4.2 4.2	232	231	<b>353</b>	AIR
* I\ <b>*</b> ^	. •	- V -			~ 41/

TRIA	554	232	353	354	AIR
TPIA	555	233	232	354	AIR
TRIA	555	233	355	355	AIR
TRIA	55.7	234	233	355	AIR
			200 355		
TRIA	57 B	234		356	1IR
TRI	520	233	₹₹. 7.44	354	AIF
TRIC	56.7	23;	7 3 5	357	VIK
TF15	5.6. <u>1</u>	235	23	357	AIR
TRIA	5 = 5	235	347	35.3	FIR
TRIA	543	237	2 ₹ 5	350	AIR
TRIA	554	237	358	359	# IR
TRIA	555	233	237	399	AIR
TRIA	556	273	339	360	AIR
TRIA	567	233	233	369	ALR
TRIA	5 = A	233	350	361	AIR
TRIA	749	241	239	361	AIP
TRIA	570	247	351	362	VIE
TRIA	571		2141		
		211		362	AIK
TRIA	572	2/1	362	363	AIR
TRIA	73	242	2 4 1	363	AIP
TPIA	7.71	51.5	363	3 5 L	AIR
TRIA	575	243	2 +2	36%	AIR
TRIA	57K	573	364	365	Alr
TRIA	577	24+	2 1 3	3.65	AIR
TRIA	578	24 +	355	36€	AIP
TRIA	579	245	2 4:4	36E	<b>FIR</b>
TRIA	5 g r	243	366	367	AIF
TRIA	581	21.5	243	367	AIR
TRIA	582	245	367	36٤	AIR
TRIA	383	217	246	368	AIR
TRIA	594	247	369	359	AIR
TRIA	6 3 5	213	247	369	AIR
TRIA	685	243	363	371;	AIR
TPIA	387	243	2 <i>4</i> ن	<b>37</b> 6	AIR
TRIA	588	573	37.	371	AIR
TRIA	589	257	2+3	371	AIR
TPIA	697	250	3.71	372	AIR
TRIA	591	251	254	<b>372</b>	AIR
TRIA	÷92	251	372	373	AIR
TRIA	503	252	251	373	AIR
TRIA	574	252	373	374	AIR
TRIA	5 a r	253	252	374	AIR
TRIA	535	253	37 L	377	AIR
TRIA	697	254	233	375	AIR
TRIA	508	25+	377	376	AIR
TRIA	509	253	234	376	AIF
TRIA	707	2° 5	276	377	AIR
TRIA	711	255	255		AIR
				3 <b>7</b> 7	
TRIA	772	255	377	378	AIR
TRIA	703	257	235	378	AIR

TRIA	700	257	378	379	AIR
TRIA	705	253	2.57	773	AIR
TRIA	716	253	779	383	AlR
TPIA	7 7 7	25.4	253	38!	AIR
TOIL	718	250	34,	391	AIR
TRIA	₹.0	2F 3	273	3.34	1 1!
Lolv	716	25.)	391	352	#IR
TRIZA	711	25 1	25.	302	DIC
TOIL	712	2:1	3 2	383	AIR
TRIA	*13	252	231	333	FIR
TPI:	714	2f 2	<b>333</b>	3.84	AIR
TRIA	717	253	232	384	AIR
TRIS	715.	St 3	384	3.85	AIK
TRIA	717	2£ +	25,3	3.85	AIR
TRIA	718	25.+	334	335	PIR
TRIA	710	253	254	385	AID
TRI4	. 5 €	283	385	3.87	ATR
TRIA	721	28 5	259	387	AIR
TRIA	772	2F5	737	38c	AIR
TRIA	723	25 1	255	358	AIR
TRIA	₹ 2 ↔	25.7	338	389	AIF
TRIA	725	253	267	389	AIR
TRIA	726	253	369	33.	PIK
TRIA	マクア	2r3	259	397	AIR
TPIA	728	263	39:	391	AIR
TRIA	25c	271	259	391	AIR
TRIA	7 🕏 ö	27 J	391	392	AIR
TRIA	731	271	271	392	AIR
TRIA	732	271	392	393	AIR
TPIA	733	272	271	393	AIR
TRIA	フマル	272	393	394	AIR
TRIA	2 ú tr	273	272	391.	AIR
TRIA	77E	27 3	371:	395	AIR
TRIA	737	27+	2/3	3 99	AIR
TRIA	778	274	395	396	AIR
TPIM	779	275	274	3 <b>9</b> 5	AIR
TRIA	74 Ç	275	396	397	AIR

## Vita

Cecil Stuerke was born 26 September 1949 in Sedalia, Missouri. He grew up in Kansas City, Kansas where he graduated from Wynadotte High School in 1967. He attended Kansas City, Kansas Community Junior College the following year. He then attended Kansas University from 1968 to 1971. Short of graduation, he enlisted in the United States Air Force. After serving one year at Richards Gerbaur Air Force Base, Grandview, Missouri, he returned to Kansas University under the Airman Education and Commissioning Program. He received Bachelor of Science Degrees in Electrical Engineering and Engineering Physics from Kansas University in 1975. He attended Officer's Training School and received an Air Force Commission on 24 March 1975. He was then assigned to the Air Force Aero-Propulsion Labortatory at Wright-Patterson Air Force Base until entering the School of Engineering, Air Force Institute of Technology in June 1979. He is a member of Eta Kappa Nu.

Permanent Address: 551 Westvale Road

Kansas City, Kansas 66102

## Vita

David W. Nordquist was born on 27 May 1952 in Chicago, Illinois. He graduated from Finneytown High School near Cincinnati, Ohio in 1970. He then attended the University of Cincinnati where he received, in 1975, the Degree of Bachelor of Science in Electrical Engineering. Shortly after graduation, he attended the Air Force Officer Training School where, in January 1976, he received his commission. He then served his first active duty assignment as a design engineer with the 6514th Test Squadron at Hill Air Force Base, Utah. He currently is assigned to the School of Engineering, Air Force Institute of Technology, Wright-Patterson Air Force Base, Ohio. He is a member of Eta Kappa Nu.

Permanent Address: 7715 Bluecrystal Court Cincinnati, OH 45224 UNCLASSIBLED
SECURITY CLASSIFICATION OF THES PAGE When Data Literal

REPORT DOCUMENTATION PAGE	BEFORE COMPLETING FORM				
AFIT/GE/EE/80D-34 AD-A100 S12	3 - RECIPIENT'S CATALOG NUMEER				
4. TITLE (and Subtitle)	5 TYPE OF REPORT & PERIOD COVERED				
THE EFFECTS OF ROTOR GEOMETRY ON THE HARMONIC PERFORMANCE OF SYNCHRONOUS	MS Thesis				
GENERATORS	6 PERFORMING ORG. REPORT NUMBER				
David W. Nordquist Cecil Stuorke Captain Captain	8. CONTRACT OR GRANT NUMBER N				
9. PERFORMING ORGANIZATION NAME FROM ADDRESS Air Force Institute of Technology Wright-Patterson Air Force Base, OH 45433	10. PROSPAN ELEMENT, PROJECT, TACK AREA & WORK UNIT NUMBERS				
1). CONTROLLING OFFICE NAME AND ADDRESS	12. REPORT DATE				
AF Wright Aeronautical Labs (POOS) Aeropropulsion Laboratory	December 1980				
Wright-Patterson Air Force Base OH 45433	121				
14. MONITORING AGENCY NAME & ADDRESS if different from Controlling Utilice)	15. SECURITY CLASS, fol this report,				
	TSA, DECLASSIFICATION DOWNGRADING SCHEDULE UNCLASSIFILID				
16. DISTRIBUTION STATEMENT (of this Report)					
Approved for public release; distribution unlimited.  17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)					
18. SUPPLEMENTARY NOTES Approved for public release	; IAW AER 190-17.				
16 JUN 1981 FREDRIC C	L. LY <b>C</b> MH, Major, USAF of Public Affairs				
19 KEY WORDS (Continue on reverse side if necessary and identify by block number) Synchronous Generators Generators					
Electric Generators Rotor Geometry					
20 ABSTRACT (Continue on reverse side II necessary and identify by block number)					
The use of rotor geometry as a specification in the control of of generator voltage and flux density harmonics is studied. The possibility of generating a specific voltage waveform at the load with only a three-phase rectifier between the AC generator and the load is investigated.					
The armature reaction MMF is expressed traveling waves with an infinite set of velothat the rotor MMF cannot cancel armature re	ocities. It is shown				

SECURITY CLASSIFICATION OF THE PAGE HE on Dath Entered

because the roter MMF has only the velocity of the rotor.

The MMFs present at all the stator slots of an armature coil group are reflected into a single slot in an attempt to control the air gap flux density harmonics be selectively positioning increments of rotor reluctance. This method fails because a general solution for the reflected flux densities could not be obtained.

Specifying the air gap reluctance incrementally as the rotor moves under successive stator slots is also tried as a means of harmonic control. This method proves unworkable due to negative MMF requirements and conflicting geometry specifications.

Finite Element analysis is introduced as a computer aid to

the design of a magnetic structure.

Recommendations for further study are included.

UNCLASSIFIED

